



Polymath garage

Xiao Tong.

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

9/7/2021

ESTIMATED REPAIR CHECKLIST

TO : LONPAC INSURANCE	VEHICLE REGISTRATION NO.: SMT8495T
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: VOLKSWAGEN / TOURAN
CLAIM TYPE : 3RD PARTY CLAIM	CHASSIS NUMBER: WVGZZZ1TZW044210
ACCIDENT DATE/TIME :	CONTACT PERSON : SEBASTIAN (97527592)

PARTS	QTY	PER UNIT	PRICES
1 FRONT BUMPER <i>Del'd</i>	1	\$ 1,258.00	\$ 1,258.00 ✓
2 REAR BUMPER SIDE HOLDER <i>Not nec</i>	2	\$ 58.00	\$ 116.00 ✓
3 FRONT BUMPER REINFORCEMENT <i>Not nec</i>	1	\$ 604.00	\$ 604.00 ✓
4 FRONT BUMPER LOWER GRILLE <i>Del'd</i>	1	\$ 198.00	\$ 198.00 ✓
5 FRONT BUMPER SIDE GRILLE LH <i>ut</i>	1	\$ 69.00	\$ 69.00 ✓
6 FRONT BUMPER SIDE LAMP LH <i>cut</i>	1	\$ 287.00	\$ 287.00 ✓
7 FRONT BUMPER SPONGE <i>cut</i>	1	\$ 95.00	\$ 95.00 ✓
8 FRONT BUMPER UNDERCOVER <i>torn</i>	1	\$ 189.00	\$ 189.00 ✓
9 FRONT BUMPER LOWER BEAM <i>Not nec</i>	1	\$ 249.00	\$ 249.00 ✓
10 FRONT BUMPER LOWER SIDE CHROME <i>ut</i>	1	\$ 48.00	\$ 48.00 ✓
11 HEADLAMP LH <i>ut</i>	1	\$ 1,738.00	\$ 1,738.00 ✓
12 FRONT GRILLE <i>cut</i>	1	\$ 685.00	\$ 685.00 ✓
13 FRONT GRILLE INNER BRACKET <i>cut</i>	1	\$ 184.00	\$ 184.00 ✓
14 FRONT GRILLE LOGO <i>Not</i>	1	\$ 82.00	\$ 82.00 ✓
		SUBTOTAL :	\$ 5,802.00
		LESS 10% :	\$ 580.20
		PARTS TOTAL :	\$ 5,221.80

4833
Less 10% : 4349.70

SPECIAL NETT	QTY	PER UNIT	PRICES
1 FRONT BUMPER CLIPS <i>3 new</i>	1 SET	\$ 30.00	\$ 30.00 ✓
2 FRONT BUMPER UNDERCOVER CLIPS	1 SET	\$ 30.00	\$ 30.00 ✓
3 FRONT GRILLE CLIPS	1 SET	\$ 20.00	\$ 20.00 ✓
		S/N TOTAL :	\$ 80.00

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 500.00	300 ✓
2 SPRAY PAINTING	\$ 500.00	250 ✓
3 WIRING	\$ 50.00	30 ✓
LABOR TOTAL :	\$ 1,050.00	

580



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 2016051237

ESTIMATE REPORT	
TOTAL PARTS COST:	\$ 5,301.80
TOTAL LABOUR COST:	\$ 1,050.00
TOTAL REPAIR COST:	\$ 6,351.80
PART BY PART / LUMP SUM:	
NO. OF REPAIR DAYS:	

SURVEYOR DETAILS	
SURVEYOR NAME:	Adrian Ly
CONTACT:	
EMAIL:	
DATE :	
TIME :	

Total: 5009.70

n/s: AK.

04 Days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____