

TP China.
Denise.

SLZ5174U 2018 May.

Honda Freed 1496cc

GBT1051090

Front LH Fender Dented	440.70	✓
Front LH Fender Inner Shield Dented	155.90	✓
Front LH Fender Inner Shield Clips ^{re}	30(SN)	✓
Front LH Fender Hybrid Emblem ^{re}	55.50	✓
Front LH Door Dented	950.40	✓
Front LH Door Lock ^{re}	262.30	+
Front LH Door Weatherstripe ^{re}	210.80	+
Front LH Door Hinge x 02 ^{re}	97.2 x 2 = 194.40	+
Front LH Wheel Rim ^{re}	680(SN) 450(SN)	
Front LH Tyre	280(SN)	+
Front LH Lower Arm ^{re}	352	+
Front LH Shock Absorber	358.40	+
Front LH Knuckle Arm	425.60	+

SLZ51744

Front LH Wheel Hub clw Bearing. 280.10 XHm

Front LH Wing Mirror Rys 680.20. X

1602.50 S.N: 480

1282.32

Panel Beating

Spray Painting. 1180

Wiring

To transfer door fittings.

To perform wheel alignment.

To dismantle front undercarriage.

~~800~~ 500.

~~800~~ 500.

~~50~~ 30

~~150~~ 80

~~150~~ 80

320.X

Total: 2952.32

L/S: 2350.

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: