

TP A19
Culic

SND 71497. 2022 Jan.

Toyota Noah ZWR800S10335

Rear Bumper	Rehnd	1025	/
Rear Bumper Clips	in	30(SN)	/
Rear Bumper Reflector x 02	MP	96 x 2 = 192	X
Rear Bumper Side Holder x 02	in	75 x 2 = 150	/
Reverse Sensor	Dmgd	280(SN)	2w(SN)
Rear End Panel	Dented	755	/
Rear End Panel Top Garnish	Rehnd	249.	/
Rear End Panel Sealant	in	60(SN)	/
Rear End Panel Antenna Sensor	Crushed	246.	/
Tailgate	Distorted	1812	/
Tailgate Lock	Dmgd	461	/
Tailgate Weatherstripe	Cut	375	/
Tailgate Inner Trim Board	Crushed	570	/
Tailgate Inner Trim Board Clips	in	30(SN)	/
Tailgate Glass Sealant	in	60(SN)	/

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SND71497.

Tailcap Lower Apron x 02

Floor Panel Top Board.

Rear Fender Inner Trim Board x 02

Rear Fender Lower Trim Board clips.

Hybrid Logo. New

$$385 \times 2 = 770 \quad \times$$

$$691 \quad \times$$

$$891 \times 2 = 1782 \quad \times$$

$$60 (SN) \quad \times$$

68 ✓ 370

5711

A283-25

S.N. 380

Panel Beating

Spray Painting.

Wiring.

To remove reverse sensor

To spray buff coat

To remove upholstery.

To remove rear camera.

To remove video recorder

To remove tailgate glass

To transfer tailgate fittings.

$$1200 \quad 900$$

$$1200 \quad 900$$

$$50 \quad 30$$

$$100 \quad 50$$

$$150 \quad 80$$

$$150 \quad 80$$

$$100 \quad 50$$

$$100 \quad 50$$

$$180 \quad 120 \quad 2340$$

$$150 \quad 80$$

total 200325

4/5 57K

06 Apr

56K