



YSK AUTO WORKSHOP

No. 1 Kaki Bukit Avenue 6 @Autobay, #01-71 Singapore 417883
UEN 53311047E

LKK Auto Consultants Pte Ltd

Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

Tax Invoice : 202202_0032
Date : 26/02/2022
Vehicle : SND7149Y
Make Model : TOYOTA NOAH 1800cc
Accident Date : 12/02/2022 16:45 (SGT)
Accident Location: SLIP ROAD FROM BEACH ROAD TO CRAWFORD ST


Particular

COST OF REPAIR & LABOUR	\$5,600.00
LOSS OF USE for 6 Days X @\$180.00 per day	\$1,080.00
Pre-Repair Inspection for 2 days x @\$180.00 per day	\$ 360.00
GIA / LTA SEARCH FEE	\$ 7.45

Singapore Dollars: Seven Thousand Forty-Seven and Cents Forty-Five Only

Total S\$: 7,047.45

=====



YSK Auto Workshop