

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 4200G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	984.50	984.50
1	TOWING COVER LH	NOT NECESSARY	49.98	-
1	TOWING COVER RH	NOT NECESSARY	49.98	-
1	REAR BUMPER LOWER SPOILER (BLACK)	CUT	290.29	290.29
1	COVER SOCKET	NECESSARY	17.61	17.61
1	PDC HOLDER LH	NECESSARY	36.27	36.27
1	PDC HOLDER RH	NECESSARY	36.27	36.27
1	REAR FOGLAMP CHROME GARNISH	NOT NECESSARY	117.58	-
1	GUIDE FOR BUMPER LH	NOT NECESSARY	188.56	-
1	GUIDE FOR BUMPER RH	NOT NECESSARY	188.56	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	600.21	-
2	WASHER-GASKET	NOT NECESSARY	29.12	-
2	ULTRASONIC SENSOR INNER	NOT NECESSARY	996.20	-
2	ULTRASONIC SENSOR OUTER	NOT NECESSARY	653.12	-
4	SENSOR BRACKET	NECESSARY	26.80	26.80
1	REAR FOGLIGHT	NOT NECESSARY	174.20	-
1	TAILPIPE TIP	NOT NECESSARY	143.97	-
			4,583.22	1,391.74
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER, LOWER SPOILER, REINFORCEMENT & ALL ACCIDENT DAMAGE ARES. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1,680.00	840.00
	TO RESPRAY REAR BUMPER.		1,000.00	800.00
	TO TRANSFER THE REVERSE SENSORS.		300.00	300.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	350.00

Report Ref No. CS/FCI22001492/Evf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NOT NECESSARY	200.00	-
			3,780.00	2,440.00
	GRAND TOTAL		8,413.22	3,851.74
	RECOMMENDED COST OF REPAIRS			3 851 74

Report Ref No. CS/FCI22001492/Evf3e2



Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.