



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042



FINALIZE COST OF REPAIRS

MS First Capital Insurance Ltd		NAME :		WIP : 52481	
36 Robinson Road		ADDRESS :		EXCESS :	
#16-01 City House				DATE: 15-Feb-22	
Singapore 068877					
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SKE4200G	DATE IN :		CONTACT PERSON :	JESS 63310685
CHASSIS NO :	WMWXS120802E80269	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	MINI One 5 Door RHD	DATE REG.:	31-Aug-17	POLICY NO. :	

NATURE OF WORKS								
		QTY	UNIT PRICE	1ST	SUPP		REVISED	PRICES
1	REAR BUMPER	1	984.50	✓		M51.12.7.380.024	984.50	984.50
2	TOWING COVER LH	1	49.98			M51.31.7.380.025		49.98
3	TOWING COVER RH	1	49.98			M51.31.7.380.026		49.98
4	REAR BUMPER LOWER SPOILER (BLACK)	1	290.29	✓		M51.12.7.380.030	290.29	290.29
5	COVER SOCKET (NEC)	1	17.61	✓		M51.12.7.382.306	17.61	17.61
6	PDC HOLDER LH (NEC)	1	36.27	✓		M51.12.7.403.267	36.27	36.27
7	PDC HOLDER RH (NEC)	1	36.27	✓		M51.12.7.403.266	36.27	36.27
8	REAR FOGLAMP CHROME GARNISH	1	117.58			M51.12.7.365.737		117.58
9	GUIDE FOR BUMPER LH	1	188.56			M51.12.7.318.755		188.56
10	GUIDE FOR BUMPER RH	1	188.56			M51.12.7.318.756		188.56
11	REAR BUMPER REINFORCEMENT	1	600.21			M51.12.7.300.788		600.21
12	WASHER-GASKET	2	14.56			B51.12.7.300.789		29.12
13	ULTRASONIC SENSOR INNER	2	498.10			M66.20.9.302.473		996.20
14	ULTRASONIC SENSOR OUTER	2	326.56			B66.20.9.274.428		653.12
15	SENSOR GASKET	4	6.70	✓		B66.20.9.283.203	26.80	26.80
16	REAR FOGLIGHT	1	174.20			M63.24.6.946.904		174.20
17	TAILPIPE TIP	1	143.97			M18.30.8.606.004		143.97

SUPPLEMENTARY								
		QTY	UNIT PRICE	1ST	SUPP		REVISED	PRICES
1								
TOTAL PARTS							1,391.74	4,583.22
TOTAL PARTS COST							1,391.74	4,583.22

Labour Description			REVISE	PRICE
1	REPLACE REAR BUMPER.		840.00	1,680.00
2	SPRAY REAR BUMPER.		800.00	1,000.00

3	TO TRANSFER THE REVERSE SENSORS.	300.00	300.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.00	250.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	350.00	350.00
6	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	-	200.00
7	SUNDRIES.	20.00	50.00
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.		TOTAL LABOUR	2,460.00 3,830.00
		TOTAL PARTS	1,391.74 4,583.22
		TOTAL	3,851.74 8,413.22
		LESS EXCESS	- -
		TOTAL AFTER EXCESS	3,851.74
		GST 7%	269.62 -
		GRAND TOTAL	4,121.36 -
		REPAIR DAYS	3.00