

ASS. REC. BY: Taughn

REF:

CTI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Lim TS

Veh No: SH6455P Yr Regn: 2018, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 398585 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH C85 / CVJ4 / 05283

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 15/2/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.I. (\$) _____

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: **15-Feb-22**

MODEL: **Hyundai Ioniq**

VEHICLE NO.: **SH 6455P**

INSURANCE: **CHINA**

MVA: **LIM T S**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Door APPS RH	1		\$80.00
	S/NETT TOTAL			\$80.00
	Labour Charge			
	Panel Beating – Rear Fender Arch RH			\$800.00
	Spray Painting – Rear Door RH			\$600.00
	TOTAL LABOUR			\$1,400.00
	ESTIMATE TOTAL			\$1,480.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphri 97495741
WP 15/2/21 @ 345pm
1/3 Resurvey after repair
2 days
Tanphri @ 9/10/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 15.02.2022 13:34

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4174594

JC NO.305504932

OMER

REGN NO.:

SH 6455P

MILEAGE

S COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

MAKE:

HYUNDAI

FUEL

ESS 383 SIN MING DRIVE

MODEL

IONIQ(G2)

DATE/TIME IN 15.02.2022 10:40

Singapore SINGAPORE 575717

(R) 65508755

(O)

YR OF MANU.

29.06.2018

TARGET DATE

(P)

CHASSIS CODE

KMHC851CVJU103283

COMPLETION DATE/TIME

UNT CARD NO.

JOB DESCRIPTION

Accident Date: 14.02.2022


ATURE: 3P 14.02.2022

NO LABOR CODE

0010 PB

DESCRIPTION

PANEL BEATING-SH 6455P



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SH 6455P

LIMITS

Vehicle No.:

SH 6455P

Service Advisor

Signature/Date

Name of Service Advisor

Date

med to Service Reception upon collection

To be kept by Security Guard