## COMFORTDELGRO ENGINEERING PIE LID

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE:

15-Feb-22

INSURANCE: CHINA C45)

MODEL:

Hyundai loniq

MVA: LIM T S

VEHICLE NO .: SH 6455P

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
18	Rear Door APPS RH	1		\$80.00 ~	4/
i	S/NETT TOTAL			\$80.00	80
	<u>Labour Charge</u> Panel Beating – Rear Fender Arch RH Spray Painting – Rear Door RH			\$800.00 \$600.00	) } }
	TOTAL LABOUR			\$1,400.00	850
	ESTIMATE TOTAL			\$1,480.00	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taughti 17415799 W 15/2/4 2 345pm

1/3 Resing affer separ 2 dezs funter a Whento a.

## LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: