

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 31 Mar 2022

Preliminary Advice

Insured : SGX7810Z
Vehicle No
TP Vehicle : SMS2611U Accident Date : 13/02/2022
No
Make : TOYOTA CAMRY Assignment Date : 16/02/2022
Date of : 21/02/2022 Est. Duration of : 5
Inspection Repair
Inspection At : PROGRESSIVE CAR CARE PTE LTD (HQ)
BLK 3022A UBI ROAD 1, #01-45/46
SINGAPORE 408716

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,206.25
Revised Amount	:S\$	6,284.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,284.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.