

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/22001494/4943**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMS 2611at Workshop m/s PA 461

of \_\_\_\_\_

Insured: SGX78102

Policy No. \_\_\_\_\_

Claims No. SNM220201086/CO2

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \$ 120k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUTDate: \_\_\_\_\_ Person Contacted: LA 49100Veh No: SMS 26114 Yr Regn: 19/2/20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota comy C.C. 2487Colour: white A/C: Insured / Std / NI / NASp. Reading: 37720 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTNB 23HK X03044723Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45ZR18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 13/2/22 D.O.I. 21/2/22

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 14k.31/3/22 P/P \$ 6284 inform Roy CRD \$ 49225, 44%.31/3/22 @ 10-34a revised to Jacqueline Tan via Messenger.

Date/Time, File Pass to?

1) 31/3 1400 ☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format: MER-TPLump Sum / I.B.I.: (\$ 6284)Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
GST:201006949C RCB NO:201006949C

not Arthur  
meray  
21/2/22  
take photo before repair  
5 days.

2/246284

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road  
Springleaf Tower #16-00  
Singapore 079909

TEL: 63896111

FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Estimate No: EST1507850

Date: 14 Feb 2022

Policy No: GA531937

Veh Reg No: SMS2611U

Make/Model: TOYOTA CAMRY  
HYBRID 2.5 ASCENT

Chassis No: JTNB23HKX03044723

Engine No: A25A5253691

Reg. Date: 19/02/2020

Your Ref No: TP 0222-6666

Claim Type: Third Party

Accident Date: 13/02/2022

TP Veh Reg No: SGX7810Z

## Estimate Repair Cost to Vehicle No :SMS2611U

| Description                                                                                                                           | U/Price           | Quantity               | Price    | Amount   |
|---------------------------------------------------------------------------------------------------------------------------------------|-------------------|------------------------|----------|----------|
|                                                                                                                                       |                   |                        | SS       | SS       |
| <b>List Price</b>                                                                                                                     |                   |                        |          |          |
| 1 REAR BOOT <i>but/gue</i>                                                                                                            | 1,143.000         | 1 PC                   | 1,143.00 | ✓        |
| 2 REAR BOOT TOP LOCK <i>twi</i>                                                                                                       | 399.0000          | 1 PC                   | 399.00   | ✓        |
| 3 REAR BOOT BOTTOM LOCK <i>17</i>                                                                                                     | 25.0000           | 1 PC                   | 25.00    | X        |
| 4 REAR BOOT TOYOTA LOGO <i>nei</i>                                                                                                    | 78.0000           | 1 PC                   | 78.00    | ✓        |
| 5 REAR BOOT CAMRY WORDING WITH GARNISH <i>17</i>                                                                                      | 222.0000          | 1 PC                   | 222.00   | X        |
| 6 REAR BOOT REFLECTOR -L/R <i>su</i>                                                                                                  | 309.0000          | 2 PC                   | 618.00   | X        |
| 7 REAR BOOT INSULATOR <i>17</i>                                                                                                       | 522.0000          | 1 PC                   | 522.00   | X        |
| 8 REAR BOOT INSULATOR CLIP <i>17</i>                                                                                                  | 5.0000            | 13 PC                  | 65.00    | X        |
| 9 REAR BOOT RUBBER <i>twi</i>                                                                                                         | 194.0000          | 1 PC                   | 194.00   | ✓        |
| 10 REAR BOOT NUMBER PLATE LAMP -L/R <i>17</i>                                                                                         | 178.0000          | 2 PC                   | 356.00   | X        |
| 11 REAR BOOT HYBRID LOGO <i>nei</i>                                                                                                   | 78.0000           | 1 PC                   | 78.00    | ✓        |
| 12 REAR BUMPER <i>dis</i>                                                                                                             | 657.0000          | 1 PC                   | 657.00   | ✓        |
| 13 REAR BUMPER CLIPS <i>nei</i>                                                                                                       | <del>5.0000</del> | <del>10 PC</del> 1 set | 50.00    | ✓        |
| 14 REAR BUMPER SIDE HOLDER -L/R <i>but</i>                                                                                            | 138.0000          | 1 PCS                  | 138.00   | ✓        |
| 15 REAR BUMPER REINFORCEMENT <i>17</i>                                                                                                | 277.0000          | 1 PC                   | 277.00   | ✓        |
| 16 REAR BUMPER REFLECTORS <i>17 n/s 5.00</i>                                                                                          | 60.0000           | 1 PC                   | 60.00    | ✓        |
| 17 REAR BUMPER CENTRE MOULDING, BLACK -L/R <i>one</i>                                                                                 | 139.0000          | 2 PC                   | 278.00   | ✓        |
| 18 REAR BUMPER SENSOR <i>shash</i>                                                                                                    | 392.0000          | 4 PC <i>392</i>        | 1,568.00 | 1 PC LH  |
| 19 REAR PANEL <i>3.6500</i>                                                                                                           | 651.0000          | 1 PC                   | 651.00   | ✓        |
| 20 REAR PANEL TOP GARNISH <i>twi</i>                                                                                                  | 296.0000          | 1 PCS                  | 296.00   | ✓        |
| 21 TAIL LAMP ASSY-L/R <i>su</i>                                                                                                       | 447.0000          | 2 PC                   | 894.00   | X        |
| 22 TAIL LAMP LOWER RETAINER -L/R <i>17</i>                                                                                            | 77.0000           | 2 PC                   | 154.00   | X        |
| 23 REAR BUMPER UNDER LOWER COVER <i>17</i>                                                                                            | 475.0000          | 1 PC                   | 475.00   | X        |
| 24 REAR SPARE TYRE BOARD <i>merged</i>                                                                                                | 548.0000          | 1 PC                   | 548.00   | ✓        |
|                                                                                                                                       |                   |                        | 9,746.00 |          |
|                                                                                                                                       |                   | Less 25%               | 2,436.50 | 7,309.50 |
| <b>Special Net</b>                                                                                                                    |                   |                        |          |          |
| 25 REAR NUMBER PLATE WITH CASING <i>su</i>                                                                                            | 35.0000           | 1 SET                  | 35.00    | X        |
|                                                                                                                                       |                   |                        | 35.00    | 35.00    |
| <b>Labour</b>                                                                                                                         |                   |                        |          |          |
| 26 TO KNOCK OUT DENTS, STRAIGHTEN REAR BOTH CHASSIS, REAR SPARE TYRE FLOOR PANEL, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS | 1,200.000         | 1 JOB                  | 1,200.00 | 850      |
| 27 TO RESPRAY PAINT ON ACCIDENT PORTIONS, PEARL                                                                                       | 1,200.000         | 1 JOB                  | 1,200.00 | 980      |
| 28 TO CHECK WIRING                                                                                                                    | 50.0000           | 1 JOB                  | 50.00    | 20       |
| 29 TO RESET CHECK LIGHT                                                                                                               | 200.0000          | 1 JOB                  | 200.00   | 50       |

Rear spare tyre from

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
GST:201006949C RCB NO:201006949C

**M/S :** CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road  
Springleaf Tower #16-00  
Singapore 079909

TEL: 63896111 FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Your Ref No: TP 0222-6666

Claim Type: Third Party

Accident Date: 13/02/2022

TP Veh Reg No: SGX7810Z

**Estimate No:** EST1507850

**Date:** 14 Feb 2022

**Policy No:** GA531937

**Veh Reg No:** SMS2611U

**Make/Model:** TOYOTA CAMRY  
HYBRID 2.5 ASCENT

**Chassis No:** JTNB23HKX03044723

**Engine No:** A25A5253691

**Reg. Date:** 19/02/2020

## Estimate Repair Cost to Vehicle No :SMS2611U

| Description                                                               | U/Price  | Quantity | Price      | Amount     |
|---------------------------------------------------------------------------|----------|----------|------------|------------|
|                                                                           |          |          | <u>S\$</u> | <u>S\$</u> |
| 30 TO TRANSFER REAR BUMPER SENSOR                                         | 100.0000 | 1 JOB    | 100.00     | 50         |
| 31 TO 4 WHEEL ALIGNMENT                                                   | 100.0000 | 1 JOB    | 100.00     | X          |
| 32 TO REMOVE, REPAIR REAR EXHAUST PIPE                                    | 100.0000 | 1 JOB    | 100.00     | X          |
| 33 TO TUFF-KOTE                                                           | 150.0000 | 1 JOB    | 150.00     | 60         |
| 34 TO REMOVE, REFIT GARNISH, CARPET, CUSHION, REAR SEAT AND RELATED PARTS | 200.0000 | 1 JOB    | 200.00     | 80         |
|                                                                           |          |          | 3,300.00   | 3,300.00   |

Total S\$ 10,644.50

Add GST @ 7% 745.12

Total Amount Payable S\$ 11,389.62

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND THREE HUNDRED EIGHTY NINE AND CENTS SIXTY TWO ONLY

**For Progressive Car Care Pte Ltd**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5892  
25%  
4194  
L-2090  
6284

11206.75

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
GST:201006949C RCB NO:201006949C

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road  
Springleaf Tower #16-00  
Singapore 079909

TEL: 63896111 FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Your Ref No: TP 0222-6666

Claim Type: Third Party

Accident Date: 13/02/2022

TP Veh Reg No: SGX7810Z

Estimate No: EST1507850

Date: 29 Mar 2022

Policy No: GA531937

Veh Reg No: SMS2611U

Make/Model: TOYOTA CAMRY  
HYBRID 2.5 ASCENT

Chassis No: JTNB23HKX03044723


Engine No: A25A5253691

Reg. Date: 19/02/2020

## Estimate Repair Cost to Vehicle No :SMS2611U

| Description                   | U/Price  | Quantity | Price      | Amount            |
|-------------------------------|----------|----------|------------|-------------------|
|                               |          |          | <u>S\$</u> | <u>S\$</u>        |
| Supplementary Parts to Repair |          |          |            |                   |
| List Price                    |          |          |            |                   |
| 1 REAR SPARE TYRE FOAM        | 353.0000 | 1 PC     | 353.00     |                   |
| 2 TAIL LAMP PANEL             | 396.0000 | 1 PC     | 396.00     |                   |
|                               |          |          | 749.00     |                   |
|                               |          | Less 25% | 187.25     | 561.75            |
| Total                         |          |          |            | S\$ 561.75        |
| GST Amount                    |          |          |            | S\$ 39.32         |
| Total Amount Payable          |          |          |            | <u>S\$ 601.07</u> |

For Progressive Car Care Pte Ltd

  
AUTHORISED SIGNATURE

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Accident Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: \_\_\_\_\_ Vehicle Registration No: SMS 2611 M

Name (as shown in NRIC): \_\_\_\_\_ NRIC/FIN/Passport No: \_\_\_\_\_

(\*Vehicle Driver/Vehicle Owner) (\*) Please delete as appropriate

Address: \_\_\_\_\_ Singapore ( )

Contact (Tel): \_\_\_\_\_ Mobile No.: \_\_\_\_\_

Email Address: \_\_\_\_\_

Date of Accident: \_\_\_\_\_ Time of Accident: \_\_\_\_\_


Place of Accident: \_\_\_\_\_

Insurance Company: \_\_\_\_\_

(B) ADDITIONAL INFORMATION /AMENDMENTS:

I have made a report on the above-mentioned accident and would like to include additional information or make the following amendments:

Further damage spotted at the centre console of the front  
panel where the panel had shifted and ~~was~~ cracked due  
to the hit impact from behind.

  
\_\_\_\_\_  
Policyholder / Driver's Signature  
Date:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:

## Vehicle Details

| Vehicle No.                      | Make / Model                                 |
|----------------------------------|----------------------------------------------|
| <b>SMS2611U</b>                  | <b>TOYOTA / CAMRY HYBRID 2.5 ASCENT</b>      |
| Vehicle Type :                   | Vehicle Attachment 1 :                       |
| <b>P10 - Passenger Motor Car</b> | <b>No Attachment</b>                         |
| Vehicle Scheme :                 | Chassis No. :                                |
| <b>Normal</b>                    | <b>JTNB23HKX03044723</b>                     |
| Propellant :                     | Engine No. :                                 |
| <b>Petrol-Electric</b>           | <b>A25A5253691</b>                           |
| Motor No. :                      | Engine Capacity :                            |
| <b>10E219705050</b>              | <b>2487 cc</b>                               |
| Power Rating :                   | Maximum Power Output :                       |
| <b>88.0 kW</b>                   | <b>160.0 kW (214 bhp)</b>                    |
| Maximum Laden Weight :           | Unladen Weight :                             |
| <b>1845 kg</b>                   | <b>1570 kg</b>                               |
| Year Of Manufacture :            | Original Registration Date :                 |
| <b>2019</b>                      | <b>19 Feb 2020</b>                           |
| Lifespan Expiry Date :           | COE Category :                               |
| <b>-</b>                         | <b>B - Car above 1600cc or 97kW (130bhp)</b> |
| Quota Premium :                  | COE Expiry Date :                            |
| <b>\$37,900.00</b>               | <b>18 Feb 2030</b>                           |
| Road Tax Expiry Date :           | PARF Eligibility Expiry Date :               |
| <b>18 Aug 2022</b>               | <b>18 Feb 2030</b>                           |
| Inspection Due Date :            | Intended Transfer Date :                     |
| <b>18 Feb 2023</b>               | <b>14 Feb 2022</b>                           |
| CO2 Emission :                   | CEV/VES Rebate Utilised Amount :             |
| <b>108.00 (g/km)</b>             | <b>\$10,000.00</b>                           |
| CO Emission :                    | HC Emission :                                |