

Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388

Yen - 67412716
 LKK - Steve.
 17/2 - 10.30am

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Ms Goh Mui Cheng 717 Woodlands Drive 70 #10-100 Singapore 730717 Mobile: 98268237
	Document No. 0	
	Document Date 15/02/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	MZAA10R	AWXBB L1	15/03/2019	SMJ6678Z	0	20677	61TP/SMJ6678Z/130222

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHY35BHX02005705	M20AN010242	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS: CHINA TAIPING ACC DATE: 13.02.2022 T/P VEH: SMY8092X DATE IN: DATE SURVEY: DATE AUTHORIZE:				50 100.00
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON REAR BUMPER, REAR PANEL AND FIX NEW PARTS	866			866 2165.00
3	B	BP-RES3 TO SPRAY PAINT ON REAR BUMPER	742			742 1855.00
4	B	BP-LAB3 TO REMOVE AND TRANSFER REAR SENSOR TO NEW BUMPER, REPLACE IF DAMAGE (NETT)				216.50
5	B	BP-LAB3 TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST (NETT)				216.50
6	B	BP-ECU3 TO RESET ECU AND REPROGRAMME (NETT)				216.50
7	L	BP-LPO SUPPLY REAR NO PLATE AND CASING (NETT)				96.00

For & on behalf of

Borneo Motors (Singapore) Pte Ltd

LKK Au Customer's Signature
 Repaired by the following:

- Please provide receipt of vehicle
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Charge Summary

Total

Less

Amount Due

Acknowledged by Repairer

Signature:

Date:

Customer Copy

Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No.2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Ms Goh Mui Cheng 717 Woodlands Drive 70 #10-100 Singapore 730717 Mobile: 98268237		
			Document No.				
			0				
			Document Date				
			15/02/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	MZAA10R	AWXBB L1	15/03/2019	SMJ6678Z	0	20677	61TP/SMJ6678Z/130222
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHY35BHX02005705		M20AN010242	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
8	B	BP-LAB3 TO REMOVE AND RE-INSTALL REAR LUGGAGE TRIM, GARNISH ETC TO ENABLE REPAIR (NETT)				3 X 433.00	
9	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.					
10	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.					
11	1	L52159-76920 COVER, RR BUMPER	1.00	844.40		844.40	
12	2	L52169-76081 COVER, RR BUMPER,	1.00	456.70		456.70	
13	3	S52161-0K040 BUMPER CLIPS	13.00	4.30		55.90	
14	4	L52162-76040 PLATE, RR BUMPER,	1.00	18.40		18.40	
15	5	L75895-78030 TAPE, MOULDING, NO.1	2.00	42.10		84.20	
16	6	L52023-76030 REINFORCEMENT	1.00	441.60		441.60	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

Inc. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462, Tel no. : 6631 1388

ESTIMATE

Account Details		Account No.		Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1		Ms Goh Mui Cheng				
		Document No. 0		717 Woodlands Drive 70 #10-100 Singapore 730717				
		Document Date 15/02/2022		Mobile: 98268237				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	MZAA10R	AWXBB L1	15/03/2019	SMJ6678Z	0	20677	61TP/SMJ6678Z/130222	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHY35BHX02005705		M20AN010242	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
17	7	L52592-76020	SEAL, RR BUMPER	1.00	90.10		90.10	
18	8	L52591-76020	SEAL, RR BUMPER	1.00	90.10		90.10	
19	9	L52576-76020	RETAINER, RR BUMPER	1.00	179.30		179.30	
20	0	L52575-76020	RETAINER, RR BUMPER	1.00	179.30		179.30	
21	1	L52461-76020	PAD, RR BUMPER	2.00	14.60		29.20	
22	2	L52461-76010	PAD, RR BUMPER	2.00	14.60		29.20	
23	3	L90467-07215	CLIP	10.00	2.70		27.00	
24	4	L89348-12070 G1	RETAINER, ULTRASONIC	2.00	44.10		88.20	
25	5	L89348-12140 G1	RETAINER, ULTRASONIC	2.00	44.10		88.20	
26	6	L89341-33220 G4	SENSOR, ULTRASONIC	2.00	490.10		980.20	
27	7	L81920-76010	REFLECTOR ASSY,	1.00	51.60		51.60	
28	8	L75606-76010	MOULDING SUB-ASSY,	1.00	387.50		387.50	
29	9	L75605-76010	MOULDING SUB-ASSY,	1.00	387.50		387.50	
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts 4,508.60		9,807.10		
				Labour 5,202.50		GST 7.00% 686.50		
				Sublet 96.00		Less 0.00		
				Lubrication/Fluid 0.00				
				Others 0.00		Amount Due 10,493.60		

Customer Copy