

SLQ9S18H. 2017 July.

TP ALG.

Xiao Long.

Mazda CX5 1998 cc

JM6KF2W7AJ0109678

|                                       |           |                    |   |
|---------------------------------------|-----------|--------------------|---|
| Front LH Fender                       | Regis     | 625.10             | + |
| Front LH Fender Arc Garnish           | wt        | 258.30             | / |
| Front LH Fender Arc Garnish clips.    | Mr        | 20(SN)             | / |
| Front LH Door                         | Distorted | 1556               | / |
| Front LH Door Lower Protector         | Delnd     | 295.60.            | / |
| Front LH Door Lock                    | Mr        | 398.40             | + |
| Front LH Door Weatherstripe.          | Mr        | 249.20             | / |
| Front LH Door Hinge x 02              | XHP Mr    | 145.1 x 2 = 290.20 | + |
| Front LH Door Check                   | XHP Mr    | 130.40             | X |
| Front LH Door Inner Trim Board        | Authnd    | 784.10             | / |
| Front LH Door Inner Trim Board clips. | XHP       | 30(SN)             | / |
| Front LH Door Glass Regulator Gear.   | Drnd      | 245.60             | ✓ |
| Front LH Door Glass Regulator Motor   | Drnd      | 326.40             | ✓ |

SLQ9518H.

Front LH Door Speaker. ~~Unknd~~ 185.40. ✓

Front LH Door Wing Mirror ~~NOLN~~ 1049.40. +

Front LH Door Wing Mirror Cover. ~~2x104.10~~ +

Front LH Door Wing Mirror Signal Lamp ~~184.10~~ +

Rear LH Door ~~Repair~~ 1380.50 +

Rear LH Door Lower Protector ~~Ut~~ 298.40. ✓

4199 6210 S.N: 50  
3359.20

Panel Beating

~~800~~ 400

Spray Painting.

~~800~~ 400

Wiring

~~50~~ 30

To spray tuff coat

960

~~150~~ 30

To transfer front and rear door fittings.

~~300~~ 80.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 4369.20

L/S: 3.5K.

04 Days.

3.5K