

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON ROAD #16-00
SPRINGLEAF TOWER SINGAPORE 079909
MOTOR CLAIMS DEPT
ATTENTION :
CONTACT : 62222366 FAX NO: 62221033

EST/QUOTE NO. SQ007147

DATE 15/02/2022
ACCIDENT DATE : 11/02/2022
VEHICLE NO : SMP7113Z
CHASSIS/ENG.NO : GB51114468
VEHICLE MODEL : HONDA FREED
CLAIM NO :
POLICY NO :
REMARK 7113CHINA TP AGST
GBK5965B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	FRT BUMPER / BR	897.00	20	717.60	717.60 /
2	1	PC	FRT BUMPER RETAINER(LH) / BR	19.50	20	15.60	15.60 /
3	1	PC	FRT BUMPER LOWER GRILLE ? X MN	180.00	20	144.00	144.00
4	1	PC	FRT BUMPER REINFORCEMENT / DD	373.20	20	298.56	298.56 /
5	10	PC	FRT BUMPER CLIPS / APC	3.80	20	3.04	30.40 /
6	1	PC	FRT GRILLE ASSY (COMPLETE) / BR	883.80	20	707.04	707.04 /
7	10	PC	FRT GRILLE CLIPS / APC	3.80	20	3.04	30.40 /
8	1	PC	FRT HEADLAMP(LH) ? X MN	1,453.30	20	1,162.64	1,162.64
9	1	PC	FRT HEADLAMP LWR BRKT LH - X MN	30.50	20	24.40	24.40
10	1	PC	FRT BONNET LOCK X AN	121.30	20	97.04	97.04
11	1	PC	FRT SUPPORT PANEL - X R	606.40	20	485.12	485.12
12	1	PC	FRT SUPPORT AIR GUIDE LH - X MN	35.20	20	28.16	28.16
13	1	PC	AIRCON CONDENSER ? X MN	985.00	20	788.00	788.00
14	1	PC	RADIATOR ASSY ? X MN	1,383.10	20	1,106.48	1,106.48
15	1	PC	REAR BUMPER / DD	819.40	20	655.52	655.52 /
16	10	PC	REAR BUMPER CLIPS / APC	3.80	20	3.04	30.40 /
17	1	PC	REAR BOOT LID / DD	1,132.90	20	906.32	906.32 /
18	1	PC	REAR BOOT INNER TRIM BOARD ? CR4	288.00	20	230.40	230.40 /
19	1	PC	REAR BOOT CENTER TRIM ? CR4	320.40 (CH)	20	256.32	256.32 /
20	1	PC	REAR NUMBER PLATE LAMP X MN	42.80	20	34.24	34.24

JANICE

PAGE: 1 of 3

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON ROAD #16-00
SPRINGLEAF TOWER SINGAPORE 079909
MOTOR CLAIMS DEPT
ATTENTION :
CONTACT : 62222366 FAX NO: 62221033

EST/QUOTE NO. SQ007147

DATE : 15/02/2022
ACCIDENT DATE : 11/02/2022
VEHICLE NO : SMP7113Z
CHASSIS/ENG.NO : GB51114468
VEHICLE MODEL : HONDA FREED
CLAIM NO :
POLICY NO :
REMARK : 7113CHINA TP AGST
GBK5965B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
21	1	PC	REAR BOOT EMBLEM / <i>mc</i>	32.10	20	25.68	25.68 ✓
22	1	PC	REAR BOOT 'FREED' LOGO / <i>mc</i>	55.00	20	44.00	44.00 ✓
23	2	PC	REAR BOOT LAMP X <i>nn</i>	363.30	20	290.64	581.28
24	1	PC	* REAR BOOT LOCK ? - <i>BT</i>	157.10	20	125.68	125.68 ✓
25	1	PC	* REAR BOOT WEATHERSTRIPE ? - <i>CR4</i>	168.00	20	134.40	134.40 ✓
26	1	PC	REAR WINDSCREEN MOULDING / <i>mc</i>	118.30	20	94.64	94.64 ✓
27	1	PC	* REAR END PANEL ? - <i>nn</i>	423.70	20	338.96	338.96 ✓
28	1	PC	* REAR END PANEL TOP GARNISH ? - <i>CR4</i>	74.30	20	59.44	59.44 ✓
SUB-TOTAL:							9,152.72

4681.32

** SPECIAL NETT PRICE **							
1	1	PC	FRT NUMBER PLATE - <i>BR</i>	35.00		35.00	35.00 ✓
2	1	PC	REAR NUMBER PLATE X <i>nn</i>	35.00		35.00	35.00 ✓
3	1	PC	REAR WINDSCREEN GUM - <i>mc</i>	40.00		40.00	40.00 ✓
4	1	PC	COOLANT ? X <i>nn</i>	40.00		40.00	40.00 ✓
5	1	PC	REAR REVERSE SENSOR - <i>Sh-ke</i>	280.00		280.00	280.00 ✓
SUB-TOTAL:							430.00

**** WORK LABOUR ****

TO KNOCK FRT BONNET, FRT FENDER LH, WELD, REMOVE & REPLACE

0.00 0.00

PAGE: 2 of 3

JANICE

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:
The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON ROAD #16-00
SPRINGLEAF TOWER SINGAPORE 079909
MOTOR CLAIMS DEPT
ATTENTION :
CONTACT : 62222366 FAX NO: 62221033

EST/QUOTE NO. SQ007147

DATE 15/02/2022
ACCIDENT DATE : 11/02/2022
VEHICLE NO : SMP7113Z
CHASSIS/ENG.NO : GB51114468
VEHICLE MODEL : HONDA FREED
CLAIM NO :
POLICY NO :
REMARK : 7113CHINA TP AGST
GBK5965B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			ABOVE PARTS	800.00		1400.00	1,400.00
			TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	800.00		1400.00	1,400.00
			TO CHECK WIRING			30.00	30.00
			TO REMOVE & REPLACE REAR WINDSCREEN			120.00	120.00
			TO TOP UP AIRCON GAS			100.00	100.00
			TO APPLY ANTI RUST COATING	1780		100.00	100.00
SUB-TOTAL							3,150.00

Steve (LKK)
16/2/22, 4.17p
m n
P/P
L B L
7 5 dys
Total - 6736.32
Supp - 1050
= 7786.32

~~Supp. Labour~~
①. To Repair / Respray the Rear floor Panel - \$480 400
②. To Remove + Refit Rear upholstery - \$250. 150
(Total phk)

~~Supp Item~~
G. Rear floor mat - \$480. / CRU

JANICE

PAGE: 3 of 3

SUB-TOTAL : S\$ 12,732.72
ADD 7% GST. S\$ 891.29
GRAND TOTAL : S\$ 13,624.01

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.