

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

AXA Ref :

Date : 24/03/2022

ATTN:THE MOTOR CLAIMS DEPT

CHINA TAIPING INSURANCE (S) PTE LTD

SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No. SMP7113Z
Date of Accident 11-Feb-22
Type of Claim TP CHINA
Survey By _____

Model / Year HONDA FREED
Policy No. _____
Prepared By SHARON
Chassis No. _____

S/NO	Description	Qty	Cost Price	Amount	
1	REAR BOOT OUTER HANDLE	1	\$ 25.00	\$ 25.00	✓ BR
2	REAR FLOOR MAT	1	\$ 600.00	\$ 600.00	✓ CRU
				\$ 625.00	625
			LESS 20 %	\$ 125.00	-20%
				\$ 750.00	500
3	TO KNOCK, SPRAY PAINTING ON REAR SPARE TYRE PANEL		\$ 400.00	✓	
4	TO REMOVE FIX UPHOLSTERY R & R rear seat & carpet		\$ 150.00	✓	
			\$ 1,300.00		550

total - 1050