



Your Ref : SNM22D201163/C02

Date: 20th May 2022

Our Ref : CS/CTI22001519/Dqy3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBF 5005Z

INSURED VEHICLE: SKL 2328Z

ACCIDENT ON 14/02/2022

Instruction was received to inspect the vehicle Reg. No. GBF 5005Z. The inspection was conducted on 16/02/2022 at the premises of M/s C. S. Ong Auto Pte Ltd, Block 10 Ang Mo Kio Industrial Park 2A #02-16 AMK Auto Point, Singapore 568047.

The following vehicle information was recorded:

Registration Number	: GBF 5005Z
Make/Model	: Nissan NV200 DX 1.6 A
Year of Registration	: 2016
Body Colour	: Grey
Chassis Number	: VM20100213
Engine Capacity	: 1597 cc

The vehicle sustained damages at the front and rear o/s portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 39,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 21,481.00
Nett Liability	<u>S\$ 17,519.00</u> =====



ANG BRYAN TANI
Automotive Assessor / Investigator



K.K. LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.