

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22001522/KPA3Q2**Date:** 13/09/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0000974
Claimant Vehicle No : SFG1798S **Insured Vehicle No :** SLL1845S
 Date of Loss: 11/02/2022 Nature of Claim: TP Claim No: MFL2022D0000842

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFG1798S**
 Make & Model: SUBARU FORESTER, 2.0 (A) Engine No: FB20YE34607
 Reg. Date: 20/11/2018 (Man. Year: 2018) Chassis No: JF1SJ5KC5JG111859
 Colour: Metallic Silver Odometer: 48622 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,394.32	888.56	505.76	36.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	765.00	475.00	38.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,634.32	1,653.56	980.76	37.23
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,634.32	1,300.00	1,334.32	50.65
+ GST 7.00/7.00% (S\$)	184.40	91.00	93.40	50.65
Nett Amount (S\$)	2,818.72	1,391.00	1,427.72	50.65
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		1,691.00		

INSPECTION

Date of Assignment: 16/02/2022
 Date Inspected: 24/02/2022 Inspected At: Kum Chew Motor Workshop (160 Sin Ming) (HQ)
 160 Sin Ming Drive, #05-08 Sin Ming Autocity
 Singapore 575722
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2022)
Parts:	M1-SUV	SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFG1798S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Bent	540.30 FL	*540.30 FL
2	2		*REAR BUMPER RETAINER	Serviceable	32.60 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	320.40 FL	*320.40 FL
4	1		*REAR END PANEL	Repair	462.70 FL	*- FL
5	2		*REAR BUMPER REFLECTOR	Serviceable	36.90 FL	*- FL
6	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
					Sub Total (\$\$)	1,672.90 1,060.70
					- List Item Discount on L Items 20.00/20.00% (\$\$)	278.58 172.14
					Total Parts (\$\$)	1,394.32 888.56

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PULL, KNOCK ON REAR ACCIDENT PORTION & CHANGE THE ABOVE PART	New	380.00	300.00
2	TO SPRAY & PAINT ON REAR ACCIDENT PORTION	New	680.00	400.00
3	TO ANTI-RUST REAR AFFECTED AREAS	New	60.00	0.00
4	TO DISMANTLE & REPLACE 1 SET REVERSE SENSOR	New	80.00	50.00
5	TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	40.00	15.00
Gross Labour Cost (\$\$)			1,240.00	765.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >