

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 14/02/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AT RENTAL

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2070093181-01

Accident Date : 24/01/2022

Vehicle No : SMN- 349-S

Make & Model : HONDA FREED 1.5G HYBRID A 1496

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	REAR BUMPER / OD	780.00	
2	REAR BUMPER RETAINER / GR	54.00	
10	REAR BUMPER CLIPS / RC	30 / 50.00	
1	TAILGATE / OD	2,175.00	1207.90
1	TAILGATE LOCK X nn	135.00	
1	EMBLEM - FREED / RC	63.00	
1	EMBLEM - HYBRID / RC	82.00	
1	REAR WINDSCREEN MOULDING / RC	90.00	
1	END PANEL X nn		
	RESTORE		

Let Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurvey
- Subject to final approval from Insurance

Knownledged by Repairer

Signature:

Date : 14/02/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AT RENTAL

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2070093181-01

Accident Date : 24/01/2022

Vehicle No : SMN- 349-S

Make & Model : HONDA FREED 1.5G HYBRID A 1496

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT BUMPER / CR4	745.00	
10	FRONT BUMPER CLIPS / MC	30 - 50.00	
1	FRONT BUMPER REINFORCEMENT ? x nn	435.00	
	Sub Total	4659.00	3081.90
	Discount 20% On Parts	(931.80)	-20%
	<u>Special Nett Item</u>		2465.51
1	REVERSE SENSOR / shld	700 - 220.00	
1	REAR WINDSCREEN SEALANT / MC	40 - 50.00	
1	FRONT NUMBER PLATE x nn	35.00	
			240

Date : 14/02/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AT RENTAL

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2070093181-01

Accident Date : 24/01/2022

Vehicle No : SMN- 349-S

Make & Model : HONDA FREED 1.5G HYBRID A 1496

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	305.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	800.00	600
	TO RESPRAY AFFECTED AREAS	800.00	600
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	150.00	120
	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	150.00	50
			1400

Steve CLKK)
17/2/22, 3.15pm

W R = 4105.52
L/S = 3284.41
= 3300
My ALY
5 Lys