



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22001529/Atf3n2	
			Date: 21/03/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDE 381B	Veh. Inspected	SKW 5741K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2200595/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	17/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JM6GJ1072G0213368	Colour	WHITE	
Odometer	111181 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/11/2021	Inspection Date	28/02/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	