

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 18/11/2021

TP Somp

Denise

LKK Auto Consultants hence notify

Reparer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

16/02/2022

Acknowledged by Repairer

Signature:

Date:

Estimated repair cost for vehicle no : SKW5741K MAZDA 6 4-DOOR SEDAN 2.0L SP.6EAT

CHASSIS: JM6GJ1072G02133689 (2015)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>del</i>	\$1,285.60	\$1,285.60 ✓
2	1	REAR BUMPER SIDE RETAINER RH <i>new</i>	\$79.80	\$79.80 \$0
3	1	REAR BUMPER REFLECTOR RH <i>new</i>	\$154.30	\$154.30 +
4	1	RH REAR FENDER <i>new</i>	\$1,254.40	\$1,254.40 +
5	1	RH REAR FENDER INNER COWLING <i>new</i>	\$254.80	\$254.80 +
6	1	RH REAR TAILLAMP <i>new</i>	\$1,598.70	\$1,598.70 +
				\$4,627.60
				LESS 20 %
				\$925.52
				SUB-TOTAL : \$3,702.08

1335
1068

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 <i>30</i>
2	1	RH REAR FENDER INNER COWLING CLIPS <i>new</i>	\$60.00	\$60.00 +
3	1	RH REAR TAILLAMP CLIPS <i>new</i>	\$4.50	\$9.00 +
4	1	REAR WINDSCREEN GLASS SEALANT <i>new</i>	\$120.00	\$120.00 +
				TOTAL: \$269.00
				TOTAL PARTS \$3,971.08

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,400.00 <i>400</i>
2	LABOUR FOR SPRAYPAINTING	\$1,000.00 <i>400</i>
3	WIRING CHECK	\$80.00 <i>30</i>
	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	\$150.00 +
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS	\$300.00 +
5	To remove reverse sensor	
		Subtotal :- \$2,930.00
		Total:- \$6,901.08

890

total: 1988

L/S: 1.6K

1.6K

Adrian King
L/S 03 days