

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22001532/AVY3N2**Date:** 28/06/2022**REFERENCE**

Insured/Claimant:	LENNY RIYANTI	Policy No:	7210154586	
Date of Loss:	24/01/2022	Nature of Claim:	OD	Claim No: 7687663561SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMF1238P</b>		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DGK013043
Reg. Date:	28/12/2021 (Man. Year: 2021)	Chassis No:	WAUZZZFV6N2026819
Colour:	Blue	Odometer:	1215 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$240,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	255/45R20	Rear Tyre Size:	255/45R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,400.00	2,621.20	7,778.80	74.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	2,552.00	2,200.00	46.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>15,152.00</b>	<b>5,173.20</b>	<b>9,978.80</b>	<b>65.86</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,060.64	362.12	698.52	65.86
<b>Nett Amount (\$\$)</b>	<b>16,212.64</b>	<b>5,535.32</b>	<b>10,677.32</b>	<b>65.86</b>

**INSPECTION**

Date of Assignment:	17/02/2022		
Date Inspected:	16/02/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER-UPPER	Repair	2,548.00 FS	*- FS
2	1		*REAR BUMPER-LOWER	Repair	1,316.00 FS	*- FS
3	2		*REAR BUMPER TRIM-LH/RH	Not Necessary	258.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Cut	968.00 FS	*774.40 FS
5	1		*REAR BUMPER TRIM-CENTER	Cut	300.00 FS	*240.00 FS
6	1		*REAR BUMPER CLOSING ELEMENT-LH	Not Necessary	318.00 FS	*- FS
7	1		*REAR BUMPER CHROME TRIM-LH	Not Necessary	287.00 FS	*- FS
8	1		*REAR BUMPER TOWING EYE COVER-LH	Not Necessary	54.00 FS	*- FS
9	1		*TAIL LIGHT-LH	Cut	779.00 FS	*622.80 FS
10	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,043.00 FS	*- FS
11	2		*REAR BUMPER SEAL-LH/RH	Not Necessary	7.00 FS	*- FS
12	1		*REAR BUMPER HOLDING STRAP	Not Necessary	189.00 FS	*- FS
13	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	95.00 FS	*- FS
14	2		*REAR PARKING AID SENSOR	Not Necessary	244.00 FS	*- FS
15	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
16	1		*BOOT LID CONTROL UNIT	Not Necessary	454.00 FS	*- FS
17	2		*REAR WHEEL ARCH COVER-LH/RH	Necessary	1,230.00 FS	*984.00 FS
18	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 10,400.00 2,621.20

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR UPPER BUMPER.REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	3,000.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$)</b>			<b>4,752.00</b>	<b>2,552.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >