

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 10 Apr 2022

## **Preliminary Advice**

|                    |                                                                                                               |                         |              |
|--------------------|---------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLE5728H                                                                                                    |                         |              |
| TP Vehicle No      | : GN6262P                                                                                                     | Accident Date           | : 11/01/2022 |
| Make               | : TOYOTA DYNA 150                                                                                             | Assignment Date         | : 17/02/2022 |
| Date of Inspection | : 18/02/2022                                                                                                  | Est. Duration of Repair | : 1          |
| Inspection At      | : JWG INTERNATIONAL PTE LTD (HQ)<br>BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK AUTOPOINT<br>SINGAPORE 568047 |                         |              |

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 18,584.39 |
| Revised Amount              | :S\$ | 200.00    |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 200.00    |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( ) Lump Sum repair

- ( X ) The above survey was conducted on a 'without prejudice' basis.