



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHALI@PREMIUMAUTO.COM.SG NOCLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0108/2022/JT
DATE : 15-Feb-22
WIP : 11386

Xiao Chun

\$19571.64.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY


#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TER LI ANN
ADDRESS : 431 KEW CRESCENT
SINGAPORE 466263
TEL EPHONE : HP +65 91850258
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900165810-02
VEHICLE NO : SMP 5396 L
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 087858
CHASSIS NO : WAUZZZF54KA077002
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Feb-22
PLACE OF ACCIDENT : SIMEI AVENUE



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: TOP-REPAIR@PREMIUMAUTOMOBILES.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5396 LE

SURVEYOR'S COMMENTARY	S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
	2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X 250 ✓
	3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS.	S/N \$ 1,700.00	X 480 ✓
	4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00	X
	5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	1000
	6	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT DOORS.	\$ 4,000.00	1100
	7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES			: \$ 12,532.00	

Handwritten signatures and initials

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408696

TEL: 6366 2323 FAX: 6341 5183

55 UBI ROAD 1, SINGAPORE 408696

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5396 LUBU FAN ACCIDENT VEHICLE REGN NO. SMP 5396 LUBU FAN

DAMAGED PAI		DAMAGED PAI	
S/N	PARTS DESCRIPTION	QTY	S/NETT
21	POP RIVET <i>2 nec</i>	4	\$ 4.00 <i>2.88</i> ✓
22	HORN - LH / RH <i>2 nec</i>	2	\$ 273.00 <i>+</i>
23	HORN SUPPORT - LH / RH	2	\$ 66.00 <i>+</i>
24	FRONT PARKING AID SENSOR - INNER <i>RH Missing</i>	2	\$ 244.00 <i>122</i> 211.76
25	FRONT PARKING AID SENSOR SEAL RING <i>Not nec</i>	4	\$ 10.00 <i>?</i> X
26	FRONT BUMPER WIRING <i>nec</i>	1	\$ 567.00 <i>+</i>
27	BONNET <i>Buckled</i>	1	\$ 3,491.00 ✓ 2792.80
28	BONNET ATTACHMENT PARTS <i>Not nec</i>	1	\$ 128.00 <i>+</i>
29	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Nec</i>	3	\$ 93.00 <i>-</i> 73.20
30	BONNET STRIKER - LH / RH <i>Not nec</i>	2	\$ 112.00 <i>+</i>
31	BONNET LOCK <i>Not nec</i>	2	\$ 455.00 <i>+</i>
32	BONNET BOWDEN CABLE - CENTER <i>?</i>	1	\$ 64.00 <i>+</i>
33	BONNET RELEASE CABLE COVER	1	\$ 11.00 <i>+</i>
34	BONNET BOWDEN CABLE - OUTER <i>Not nec</i>	1	\$ 64.00 <i>+</i>
35	BONNET RELEASE LEVER	1	\$ 15.00 <i>+</i>
36	HEADLIGHT - LH / RH <i>2 LH cracked</i>	2	\$ 16,832.00 <i>+</i> 6732.80 ✓
37	LIFT CYLINDER - LH / RH <i>Not nec</i>	2	\$ 434.00 <i>+</i>
38	LIFT CYLINDER CORRUGATED PIPE <i>Not nec</i>	1	\$ 100.00 <i>+</i>
39	LOCK CARRIER <i>Not nec</i>	1	\$ 1,127.00 <i>+</i>
40	LOCK CARRIER SUPPORT - LH / RH <i>Not nec cracked</i>	2	\$ 85.00 <i>+</i> 33.84 ✓

SUB TOTAL SPARE PARTS

: \$ 24,175.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408655

TEL: 4366 2423 FAX: 6541 1183

EMAIL: INFO@KHAOSARA.COM HONGKONG@KHAOSARA.COM SINGAPORE@KHAOSARA.COM

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5396 LINT HUI ACCIDENT VEHICLE REGN NO. SW
SERVICES

UPHOLDING S/N

PARTS DESCRIPTION

QTY

DAMAGED PARTS & PRICES

S/NETT REMARKS

41	CHARGED AIR COOLER	Not New Dented	1	\$	654.00	522.80 ✓
42	CHARGED AIR COOLER PRESSURE HOSE - RH	? Not New	1	\$	413.00	+
43	CHARGED AIR COOLER PRESSURE PIPE		1	\$	496.00	+
44	A/C CONDENSER	Not New	1	\$	683.00	+
45	OUTSIDE TEMPERATURE SENSOR BRACKET	New	1	\$	21.00	16.32 ✓
46	RADIATOR	Not New	1	\$	1,010.00	+
47	RADIATOR COOLANT	Not New	6	\$	282.00	+
48	RADIATOR AIR GUIDE OUTER - LH / RH	? Not New	2	\$	72.00	? X
49	RADIATOR AIR GUIDED INNER - LH / RH		2	\$	38.00	? X
50	RADIATOR AIR GUIDE UPPER	? Not New	1	\$	19.00	? X
51	RADIATOR AIR GUIDE LOWER		1	\$	25.00	? X
52	FRONT NO PLATE	Dented	S/N	\$	60.00	✓
53	SUNDRIES	New		\$	350.00	45.84 ✓

TOTAL SPARE PARTS	:	\$ 37,778.00
TOTAL LABOUR CHARGES	:	\$ 12,532.00
GRAND TOTAL	:	\$ 50,310.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

 LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 USI ROAD 1 SINGAPORE 48689

TEL 6366 2323 FAX 6341 1183

1154H, NORA KHAI, PREMIUM AUTOMOBILES PTE LTD

NAME

Adrian Li

SURVEYED DATE

16/02/22

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Xbl Authorized, 04 Days.

ll/s

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT