

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0108/2022/JT
DATE : 15-Feb-22
WIP : 11386

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Adrian
4 days - ok - John
7-Jul-22*

OWNER'S NAME : MS TER LI ANN
ADDRESS : 431 KEW CRESCENT
SINGAPORE 466263
TELEPHONE : HP +65 91850258
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900165810-02
VEHICLE NO : **SMP 5396 L**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 087858
CHASSIS NO : WAUZZZF54KA077002
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Feb-22
PLACE OF ACCIDENT : SIMEI AVENUE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5396 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$	1,700.00	\$	480.00
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$	560.00		
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,800.00	\$	1,000.00
6	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT DOORS.	\$	4,000.00	\$	1,100.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 12,532.00	\$	3,502.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5396 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,787.00	\$	1,787.00
2	FRONT BUMPER FIXING PARTS	1	\$ 425.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	\$	174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 254.00		
6	FRONT BUMPER SPOILER	1	\$ 599.00		
7	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 144.00		
8	RADIATOR GRILLE	1	\$ 2,576.00	\$	2,060.80
9	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 116.00	\$	45.76
10	RADIATOR GRILLE COVER - UPPER	1	\$ 209.00		
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,058.00	\$	423.20
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	\$	110.80
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	\$	719.20
14	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00		
15	FRONT BUMPER BRACKET - LH / RH	2	\$ 508.00		
16	FRONT BUMPER TOP COVER	1	\$ 143.00	\$	114.00
17	CAUTION STICKER	1	\$ 16.00	\$	12.40
18	AIR COND STICKER	1	\$ 9.00	\$	6.64
19	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	\$	122.80
20	FRONT BUMPER LOCK CARRIER BRACKET SUPPORT - LH / RH	2	\$ 64.00		
SUB TOTAL SPARE PARTS			\$ 9,480.00	\$	5,577.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5396 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	5,577.40
21	POP RIVET	4	\$ 4.00	\$	2.88
22	HORN - LH / RH	2	\$ 273.00		
23	HORN SUPPORT - LH / RH	2	\$ 66.00		
24	FRONT PARKING AID SENSOR - INNER	2	\$ 244.00	\$	211.76
25	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00		
26	FRONT BUMPER WIRING	1	\$ 567.00		
27	BONNET	1	\$ 3,491.00	\$	2,792.80
28	BONNET ATTACHMENT PARTS	1	\$ 128.00		
29	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	\$	73.20
30	BONNET STRIKER - LH / RH	2	\$ 112.00		
31	BONNET LOCK	2	\$ 455.00		
32	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00		
33	BONNET RELEASE CABLE COVER	1	\$ 11.00		
34	BONNET BOWDEN CABLE - OUTER	1	\$ 64.00		
35	BONNET RELEASE LEVER	1	\$ 15.00		
36	HEADLIGHT - LH / RH	2	\$ 16,832.00	\$	6,732.80
37	LIFT CYLINDER - LH / RH	2	\$ 434.00		
38	LIFT CYLINDER CORRUGATED PIPE	1	\$ 100.00		
39	LOCK CARRIER	1	\$ 1,127.00		
40	LOCK CARRIER SUPPORT - LH / RH	2	\$ 85.00	\$	33.84
SUB TOTAL SPARE PARTS		:	\$ 24,175.00	\$	15,424.68

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5396 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 15,424.68</i>
41	CHARGED AIR COOLER	1	\$ 654.00	<i>\$ 522.80</i>
42	CHARGED AIR COOLER PRESSURE HOSE - RH	1	\$ 413.00	
43	CHARGED AIR COOLER PRESSURE PIPE	1	\$ 496.00	
44	A/C CONDENSER	1	\$ 683.00	
45	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	<i>\$ 16.32</i>
46	RADIATOR	1	\$ 1,010.00	
47	RADIATOR COOLANT	6	\$ 282.00	
48	RADIATOR AIR GUIDE OUTER - LH / RH	2	\$ 72.00	
49	RADIATOR AIR GUIDED INNER - LH / RH	2	\$ 38.00	
50	RADIATOR AIR GUIDE UPPER	1	\$ 19.00	
51	RADIATOR AIR GUIDE LOWER	1	\$ 25.00	
52	FRONT NO PLATE	S/N	\$ 60.00	<i>\$ 60.00</i>
53	SUNDRIES		\$ 350.00	<i>\$ 45.84</i>
TOTAL SPARE PARTS			\$ 37,778.00	<i>\$ 16,069.64</i>
TOTAL LABOUR CHARGES			\$ 12,532.00	<i>\$ 3,502.00</i>
GRAND TOTAL			\$ 50,310.00	<i>\$ 19,571.64</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-21/04/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT