

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0107/2022/JT  
DATE : 15-Feb-22  
WIP : 11746

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/22

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

Hi Adrian,

6 days - ok - Jy - 14 Apr 22

OWNER'S NAME : MR TAN SAIK HUAT  
ADDRESS : 28 PARBURY AVENUE  
#03-02  
SINGAPORE 457298  
TELEPHONE : HP +65 90679077  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7210081540  
VEHICLE NO : **SNB 296 L**  
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC  
MODEL YEAR : 28/07/2021  
ENGINE NO : DEM 032018  
CHASSIS NO : WAUZZZF44MN0012721  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 12-Feb-22  
PLACE OF ACCIDENT : FORT ROAD TURNING TO ECP

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 296 L**

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO REMOVE ND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$	1,400.00	\$	480.00
4	TO CARRY OUT PRESURISE, VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00		
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00		
<b>SUB TOTAL LABOUR CHARGES</b>		:	<b>\$ 3,710.00</b>	<b>\$</b>	<b>1,210.00</b>

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 296 L**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>C/F</i>		\$ 1,210.00
	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER.		
6	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,550.00	\$ 1,000.00
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER AND LHS FRONT DOOR.	\$ 4,000.00	\$ 1,100.00
8	SUPPLEMENTARY	\$ 780.00	\$ 780.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 13,232.00</b>	<b>\$ 4,282.00</b>

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 296 L**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	\$ 1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 393.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	\$ 174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 293.00	
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 51.00	
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	1	\$ 293.00	\$ 234.00
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00	
9	FRONT BUMPER TRIM - LH	1	\$ 54.00	
10	RADIATOR GRILLE	1	\$ 1,754.00	\$ 1,403.20
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 212.00	\$ 169.20
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	\$ 719.20
13	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00	
14	FRONT BUMPER BRACKET - LH	1	\$ 254.00	\$ 203.20
15	FRONT BUMPER TOP COVER	1	\$ 143.00	\$ 114.00
16	CAUTION STICKER	1	\$ 16.00	\$ 12.40
17	AIR COND STICKER	1	\$ 9.00	\$ 6.64
18	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	\$ 122.80
19	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	\$ 51.04
20	POP RIVET	4	\$ 4.00	\$ 2.88
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 7,501.00</b>	<b>\$ 5,114.96</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 296 L**

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	5,114.96
21	HORN - LH	1	\$ 134.00		
22	HORN SUPPORT - LH	1	\$ 33.00		
23	FRONT PARKING AID SENSOR - INNER / OUTER	3	\$ 488.00		
24	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00		
25	FRONT BUMPER WIRING SET	1	\$ 642.00		
26	BONNET	1	\$ 3,425.00	\$	2,740.00
27	BONNET ATTACHMENT PARTS	1	\$ 431.00		
28	BONNET HINGE - LH / RH	2	\$ 680.00		
29	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	\$	73.20
30	HEADLAMPS COVER - LH	1	\$ 49.00		
31	BONNET STRIKER - LH	1	\$ 56.00		
32	BONNET LOCK	1	\$ 228.00		
33	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00		
34	BONNET RELEASE CABLE COVER	1	\$ 11.00		
35	BONNET BOWDEN CABLE - OUTER	1	\$ 64.00		
36	BONNET RELEASE LEVER	1	\$ 15.00		
37	BONNET LOCK CABLE	1	\$ 82.00		
38	FRONT WHEEL HOUSING LINER - LH	1	\$ 256.00		
39	FRONT WHEEL SPOILER - LH	1	\$ 82.00		
40	FRONT WHEEL SPOILER LOWER - LH	1	\$ 39.00		
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 6,882.00</b>	<b>\$</b>	<b>7,928.16</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 296 L**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F	\$	7,928.16
41	HEADLIGHT - LH	1 \$	8,172.00	\$ 6,537.60
42	LIFT CYLINDER - LH	1 \$	231.00	
43	LIFT CYLINDER CORRUGATED PIPE	1 \$	107.00	
44	LOCK CARRIER	1 \$	1,127.00	
45	LOCK CARRIER SUPPORT - LH	1 \$	43.00	
46	A/C CONDENSER	1 \$	683.00	
47	OUTSIDE TEMPRATURE SENSOR BRACKET	1 \$	21.00	\$ 16.32
48	CHAGRED AIR COOLER	1 \$	654.00	\$ 522.80
49	CHARGED AIR COOLER PRESSURE HOSE - LH	1 \$	496.00	
50	RADIATOR	1 \$	699.00	
51	RADIATOR COOLANT	6 \$	282.00	
52	RADIATOR AIR GUIDE OUTER- LH / RH	2 \$	102.00	\$ 40.08
53	RADIATOR AIR GUIDE INNER - LH / RH	2 \$	38.00	\$ 14.64
54	RADIATOR AIR GUIDE UPPER	1 \$	19.00	
55	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
56	SUNDRIES	\$	400.00	\$ 90.24
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 27,517.00</b>	<b>\$ 15,209.84</b>
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 13,232.00</b>	<b>\$ 4,282.00</b>
<b>GRAND TOTAL</b>		:	<b>\$ 40,749.00</b>	<b>\$ 19,491.84</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 BL-30/03/22



## Supplementary Estimate-1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

**Estimate No.**
**Date**
**Service Advisor**
**Pages**
**Regn No**
**Model No**

PA/OD/0107/2022/JT

25-Feb-22

CHANG

1 of 1

SNB 296 L

AUDI A4 2.0 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

**Labours**

1	TO DISLodge AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT REINFORCEMENT BEAM BRACKET.	S/N	\$ 780.00	\$ 780.00 (A)
---	---	-----	-----------	---------------

**GRAND TOTAL**

\$ 780.00 \$ 780.00

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT