

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Xiao Chun.

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0107/2022/JT
25-Feb-22
CHANG
1 of 1
SNB 296 L
AUDI A4 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT REINFORCEMENT BEAM BRACKET.	\$ 780.00	✓
GRAND TOTAL		\$ 780.00	

For Premium Automobiles Pte Ltd

Adrian Ling
HLG



Authorised Signature

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL 6365 2323 FAX 6341 1183

EMAIL: NOVA@PREMIUMAUTO.COM.SG CLAIM@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 296 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 <i>250</i>	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,400.00 ? <i>=480</i>	<i>slg.</i>
4	TO CARRY OUT PRESURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 *	
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00 *	
SUB TOTAL LABOUR CHARGES		: \$ 3,710.00	

Car in 23/2/02

wip: 11746.

kiam/

PREMIUM AUTOMOBILES

50 LEE ROAD 1, SINGAPORE 408649

TEL: 5761 2123 FAX: 5741 1153

FINE LINE MOTOR CARRIAGES (P) LTD. 50 LEE ROAD 1, SINGAPORE 408649

ESTIMATE MATERIAL LIST FOR ACCIDENT VEHICLE REG NO. **SNB206L**

AIG - Adrian

- 4 days

ESTIMATE PARTS & PR

S/N	REMARKS	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1		FRONT BUMPER <i>rehd</i>	1	\$ 2,377.00	✓
2		FRONT BUMPER FIXING PARTS <i>neu</i>	1	\$ 393.00	+
3		FRONT BUMPER SECURING STRIP <i>?</i>	2	\$ 79.00	?
4		FRONT BUMPER GRILLE - CENTER <i>could</i>	1	\$ 219.00	✓
5		FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>?</i>	1	\$ 293.00	?
6		FRONT BUMPER AIR GUIDE - LH <i>neu</i>	1	\$ 51.00	+
7		FRONT BUMPER CLOSING ELEMENT - UPPER CENTER <i>could</i>	1	\$ 293.00	✓ <i>h.s.</i>
8		FRONT BUMPER AIR GUIDE GRILLE - LH <i>?</i>	1	\$ 151.00	?
9		FRONT BUMPER TRIM - LH <i>neu</i>	1	\$ 54.00	+
10		RADIATOR GRILLE <i>could</i>	1	\$ 1,754.00	✓
11		FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1	\$ 212.00	✓
12		FRONT BUMPER REINFORCEMENT BEAM <i>Best</i>	1	\$ 899.00	✓
13		FRONT BUMPER GUIDE SECTION - LH / RH <i>neu</i>	2	\$ 82.00	+
14		FRONT BUMPER BRACKET - LH <i>Best</i>	1	\$ 254.00	✓ <i>h.s.</i>
15		FRONT BUMPER TOP COVER <i>?</i>	1	\$ 143.00	?
16		CAUTION STICKER <i>?</i>	1	\$ 16.00	?
17		AIR COND STICKER <i>?</i>	1	\$ 9.00	?
18		FRONT BUMPER LOCK CARRIER BRACKET <i>could</i>	1	\$ 154.00	✓
19		FRONT BUMPER SUPPORT LH / RH <i>Best</i>	2	\$ 64.00	✓ <i>h.s.</i>
20		POP RIVET <i>neu</i>	4	\$ 4.00	✓
SUB TOTAL SPARE PARTS			:	\$ 7,501.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408689

TEL: 6368 2323 FAX: 6841 1183

EMAIL: NORA@HARGREAVESPREMIUMAUTOS.COM.SG/CLAMS@PREMIUMAUTOS.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO: SVB296C

DAMAGED PARTS & PRICED PARTS & PRICED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	RESINETT	REMARKS
-----	-------------------	-----	----------	---------

41	HEADLIGHT - LH <i>ut</i>	1	\$ 8,172.00	✓
42	LIFT CYLINDER - LH	1	\$ 231.00	✓
43	LIFT CYLINDER CORRUGATED PIPE <i>Free m</i>	1	\$ 107.00	✓
44	LOCK CARRIER <i>?</i>	1	\$ 1,127.00	?
45	LOCK CARRIER SUPPORT - LH <i>?</i>	1	\$ 43.00	?
46	A/C CONDENSER <i>?</i>	1	\$ 683.00	?
47	OUTSIDE TEMPRATURE SENSOR BRACKET <i>ut</i>	1	\$ 21.00	✓
48	CHAGRED AIR COOLER <i>Dented</i>	1	\$ 654.00	✓ <i>ll/s</i>
49	CHARGED AIR COOLER PRESSURE HOSE - LH <i>?</i>	1	\$ 496.00	?
50	RADIATOR <i>?</i>	1	\$ 699.00	?
51	RADIATOR COOLANT <i>?</i>	6	\$ 282.00	?
52	RADIATOR AIR GUIDE OUTER - LH / RH <i>2H Dented</i>	2	\$ 102.00	✓ <i>51? ll/s</i>
53	RADIATOR AIR GUIDE INNER - LH / RH <i>LH Dented</i>	2	\$ 38.00	✓ <i>19. ll/s</i>
54	RADIATOR AIR GUIDE UPPER <i>?</i>	1	\$ 19.00	?
55	FRONT NO PLATE <i>Best</i>	S/N	\$ 60.00	✓
56	SUNDRIES <i>?</i>		\$ 400.00	?

TOTAL SPARE PARTS	:	\$ 27,517.00
TOTAL LABOUR CHARGES	:	\$ 12,452.00
GRAND TOTAL	:	\$ 39,969.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED; REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.