



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

SKU47881 356222

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0107/2022/JT
DATE : 15-Feb-22
WIP : 11746

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN SAIK HUAT
ADDRESS : 28 PARBURY AVENUE
#03-02
SINGAPORE 457298
TELEPHONE : HP +65 90679077
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210081540
VEHICLE NO : **SNB 296 L**
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 28/7/2021
ENGINE NO : DEM 032018
CHASSIS NO : WAUZZZF44MN0012721
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Feb-22
PLACE OF ACCIDENT : FORT ROAD TURNING TO ECP



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHIN@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 296 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,400.00	? 480 ✓
4	TO CARRY OUT PRESURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	+
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	+
SUB TOTAL LABOUR CHARGES		: \$ 3,710.00	



ADD 1 SINGAPORE 55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6844 1183

55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6844 1183

EMAIL: NGRAHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 290 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,550.00	1000 ✓ (Without lock carrier) 2250 (With lock carrier)
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER AND LHS FRONT DOOR.	\$	4,000.00	1100 ✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$	12,452.00

ITEMS & PRICES	ESTIMATED	REMARKS	DAMAGED PARTS & PRICES
QTY	S/NETT	REMARKS	NATURE OF JOBS
QTY	S/NETT	REMARKS	NATURE OF JOBS
1	FRONT BUMPER	Rehd	1 \$ 2,377.00 ✓ 1901.60
2	FRONT BUMPER FIXING PARTS	neu	1 \$ 393.00 +
3	FRONT BUMPER SECURING STRIP	? NN	2 \$ 79.00 ? X
4	FRONT BUMPER GRILLE - CENTER	curled	1 \$ 219.00 ✓ 174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	? NN	1 \$ 293.00 ? X
6	FRONT BUMPER AIR GUIDE - LH	neu	1 \$ 51.00 +
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	? cra	1 \$ 293.00 234 ✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH	? NN	1 \$ 151.00 ? X
9	FRONT BUMPER TRIM - LH	neu	1 \$ 54.00 +
10	RADIATOR GRILLE	curled	1 \$ 1,754.00 ✓ 1403.20
11	FRONT BUMPER FOAM FILLER PIECE	curled	1 \$ 212.00 ✓ 169.20
12	FRONT BUMPER REINFORCEMENT BEAM	Bent	1 \$ 899.00 ✓ 719.20
13	FRONT BUMPER GUIDE SECTION - LH / RH	neu	2 \$ 82.00 +
14	FRONT BUMPER BRACKET - LH	? Bent	1 \$ 254.00 ? 203.20 ✓
15	FRONT BUMPER TOP COVER	? deformed	1 \$ 143.00 ? 114 ✓
16	CAUTION STICKER	? nec	1 \$ 16.00 ? 12.40 ✓
17	AIR COND STICKER	? nec	1 \$ 9.00 ? 6.64 ✓
18	FRONT BUMPER LOCK CARRIER BRACKET	? cracked	1 \$ 154.00 ? 122.80 ✓
19	FRONT BUMPER SUPPORT - LH / RH	? Damaged	2 \$ 64.00 ? 51.04 ✓
20	POP RIVET	? nec	4 \$ 4.00 ? 2.88 ✓
SUB TOTAL SPARE PARTS		:	\$ 7,501.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

AD 1, SINGAPORE 455 UBI ROAD 1, SINGAPORE 408699

2323 FAX 6341 1183 TEL 6366 2323 FAX 6341 1183

EMAIL: JDR&K@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

VEHICLE MATERIAL LIST FOR ACCIDENT VEHICLE REG NO: SIB-296 L

ESTIMATED PARTS & PRICES
 ESTIMATED PARTS & PRICES
 ESTIMATED

REMARKS	S/N	PARTS DESCRIPTION	QTY	S/NETT	SIGNATURE OF	REMARKS
	21	HORN - LH	1	\$	134.00	+
	22	HORN SUPPORT - LH	1	\$	33.00	+
	23	FRONT PARKING AID SENSOR - INNER / OUTER	3	\$	488.00	+
	24	FRONT PARKING AID SENSOR SEAL RING	4	\$	10.00	+
	25	FRONT BUMPER WIRING SET	1	\$	642.00	+
	26	BONNET	1	\$	3,425.00	- 2740
	27	BONNET ATTACHMENT PARTS	1	\$	431.00	+
	28	BONNET HINGE - LH / RH	2	\$	680.00	+
	29	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$	93.00	✓ 73.20
	30	HEADLAMPS COVER - LH	1	\$	49.00	? X
	31	BONNET STRIKER - LH	1	\$	56.00	+
	32	BONNET LOCK	1	\$	228.00	+
	33	BONNET BOWDEN CABLE - CENTER	1	\$	64.00	+
	34	BONNET RELEASE CABLE COVER	1	\$	11.00	+
	35	BONNET BOWDEN CABLE - OUTER	1	\$	64.00	+
	36	BONNET RELEASE LEVER	1	\$	15.00	+
	37	BONNET LOCK CABLE	1	\$	82.00	+
	38	FRONT WHEEL HOUSING LINER - LH	1	\$	256.00	+
	39	FRONT WHEEL SPOILER - LH	1	\$	82.00	+
	40	FRONT WHEEL SPOILER LOWER - LH	1	\$	39.00	+

SUB TOTAL SPARE PARTS : \$ 6,882.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO: SIB 296 L

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	UNIT	PRICE	NETT	REMARKS
41	HEADLIGHT - LH <i>ut</i>	1	\$	8,172.00	✓	6537.60
42	LIFT CYLINDER - LH	1	\$	231.00	✓	
43	LIFT CYLINDER CORRUGATED PIPE <i>free</i>	1	\$	107.00	✓	
44	LOCK CARRIER <i>? NN</i>	1	\$	1,127.00	? X	
45	LOCK CARRIER SUPPORT - LH <i>? NN</i>	1	\$	43.00	? X	
46	A/C CONDENSER <i>? NN</i>	1	\$	683.00	? X	
47	OUTSIDE TEMPRATURE SENSOR BRACKET <i>ru</i>	1	\$	21.00	✓	16.32
48	CHAGRED AIR COOLER <i>? Dented</i>	1	\$	654.00	? ✓	522.80 ✓
49	CHARGED AIR COOLER PRESSURE HOSE - LH <i>? NN</i>	1	\$	496.00	? X	
50	RADIATOR <i>? NN</i>	1	\$	699.00	? X	
51	RADIATOR COOLANT <i>? NN</i>	6	\$	282.00	? X	
52	RADIATOR AIR GUIDE OUTER- LH / RH <i>? LH Deformed</i>	2	\$	102.00	? ✓	40.08 ✓
53	RADIATOR AIR GUIDE INNER - LH / RH <i>? LH Deformed</i>	2	\$	38.00	? ✓	14.64 ✓
54	RADIATOR AIR GUIDE UPPER <i>? NN</i>	1	\$	19.00	? X	
55	FRONT NO PLATE <i>Bent</i>	S/N	\$	60.00	✓	
56	SUNDRIES <i>? nec</i>		\$	400.00	? ✓	90.24 ✓

TOTAL SPARE PARTS	:	\$	27,517.00
TOTAL LABOUR CHARGES	:	\$	12,452.00
GRAND TOTAL	:	\$	39,969.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES PTE LTD



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Adrian
16/02/22

Not Authorised, 04 days (Without lode carrier)
07 Days (With lode carrier).

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: