

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 - FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0107/2022/JT
DATE : 15-Feb-22
WIP : 11746

Xiao Chun.

\$19491.84

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN SAIK HUAT
ADDRESS : 28 PARBURY AVENUE
#03-02
SINGAPORE 457298
TELEPHONE : HP +65 90679077
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210081540
VEHICLE NO : SNB 296 L
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 28/7/2021
ENGINE NO : DEM 032018
CHASSIS NO : WAUZZZF44MN0012721
MIL EAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Feb-22
PLACE OF ACCIDENT : FORT ROAD TURNING TO ECP

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699

TEL: 6346 2323 FAX: 6341 1183

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE 9NB 296 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,400.00	480.
4	TO CARRY OUT PRESURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	*
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM, TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	*
SUB TOTAL LABOUR CHARGES		: \$ 3,710.00	

PREMIUM AUTOMOBILES



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE S/NB-290 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,550.00	88.8. 1000 (Without lock carrier) 2250 (With lock carrier)
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER AND LHS FRONT DOOR.	\$ 4,000.00	1100
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,452.00	

PREMIUM AUTOMOBILES

55 LORRAINE ROAD, SINGAPORE 408695

TEL: 6366 2121 FAX: 6341 3193

FAX: 6366 2121 FAX: 6341 3193

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO 3N3-253 E

PA PRICES

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1	\$ 2,377.00	✓
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 393.00	+
3	FRONT BUMPER SECURING STRIP <i>Neu</i>	2	\$ 79.00	?
4	FRONT BUMPER GRILLE - CENTER <i>Curled</i>	1	\$ 219.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>Neu</i>	1	\$ 293.00	?
6	FRONT BUMPER AIR GUIDE - LH <i>Neu</i>	1	\$ 51.00	+
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER <i>Curled</i>	1	\$ 293.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Neu</i>	1	\$ 151.00	+
9	FRONT BUMPER TRIM - LH <i>Neu</i>	1	\$ 54.00	+
10	RADIATOR GRILLE <i>Curled</i>	1	\$ 1,754.00	✓
11	FRONT BUMPER FOAM FILLER PIECE <i>Curled</i>	1	\$ 212.00	✓
12	FRONT BUMPER REINFORCEMENT BEAM <i>Bent</i>	1	\$ 899.00	✓
13	FRONT BUMPER GUIDE SECTION - LH / RH <i>Neu</i>	2	\$ 82.00	+
14	FRONT BUMPER BRACKET - LH <i>Bent</i>	1	\$ 254.00	✓
15	FRONT BUMPER TOP COVER <i>Rehd</i>	1	\$ 143.00	✓
16	CAUTION STICKER <i>Neu</i>	1	\$ 16.00	✓
17	AIR COND STICKER <i>Neu</i>	1	\$ 9.00	✓
18	FRONT BUMPER LOCK CARRIER BRACKET <i>Curled</i>	1	\$ 154.00	✓
19	FRONT BUMPER SUPPORT - LH / RH <i>Damaged.</i>	2	\$ 64.00	✓
20	POP RIVET <i>Neu</i>	4	\$ 4.00	✓
SUB TOTAL SPARE PARTS		:	\$ 7,501.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

ENDING PREMIUM AUTOMOBILES



55 ABLE ROAD 1, SINGAPORE 405699
TEL: 6396 2221, FAX: 5941 1183

MATERIAL LIST FOR ACCIDENT VEHICLE REG NO: SWB 296 L

REPAIR PARTS & DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN - LH <i>34 m</i>	1	\$	134.00 +
22	HORN SUPPORT - LH	1	\$	33.00 +
23	FRONT PARKING AID SENSOR - INNER / OUTER <i>34 m</i>	3	\$	488.00 +
24	FRONT PARKING AID SENSOR SEAL RING	4	\$	10.00 +
25	FRONT BUMPER WIRING SET <i>34 m</i>	1	\$	642.00 +
26	BONNET <i>Dented</i>	1	\$	3425.00 -
27	BONNET ATTACHMENT PARTS <i>34 m</i>	1	\$	431.00 +
28	BONNET HINGE - LH / RH <i>34 m</i>	2	\$	680.00 +
29	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>34 m</i>	3	\$	93.00 ✓
30	HEADLAMPS COVER - LH <i>34 m</i>	1	\$	49.00 +
31	BONNET STRIKER - LH <i>34 m</i>	1	\$	56.00 +
32	BONNET LOCK <i>34 m</i>	1	\$	228.00 +
33	BONNET BOWDEN CABLE - CENTER <i>2</i>	1	\$	64.00 +
34	BONNET RELEASE CABLE COVER	1	\$	11.00 +
35	BONNET BOWDEN CABLE - OUTER	1	\$	64.00 +
36	BONNET RELEASE LEVER	1	\$	15.00 +
37	BONNET LOCK CABLE <i>34 m</i>	1	\$	82.00 +
38	FRONT WHEEL HOUSING LINER - LH	1	\$	256.00 +
39	FRONT WHEEL SPOILER - LH	1	\$	82.00 +
40	FRONT WHEEL SPOILER LOWER - LH	1	\$	39.00 +

SUB TOTAL SPARE PARTS

: \$ 6,882.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



65 QUEEN ROAD 1, SINGAPORE 408899

TEL: 6386 2529 FAX: 6841 1183

EMAIL: NORAH@PREMIUMAUTOMOBILES.COM SINGAPORE

INVENTORY MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO: SNE 296 E

DATE: 01/01/2001 TIME: 10:00 AM

S/N	PARTS DESCRIPTION	QTY	NETT	REMARKS
41	HEADLIGHT - LH <i>ut</i>	1	\$ 8,172.00	✓
42	LIFT CYLINDER - LH	1	\$ 231.00	+
43	LIFT CYLINDER CORRUGATED PIPE <i>face m</i>	1	\$ 107.00	+
44	LOCK CARRIER <i>the new</i>	1	\$ 1,127.00	+
45	LOCK CARRIER SUPPORT - LH <i>the new</i>	1	\$ 43.00	+
46	A/C CONDENSER <i>the new</i>	1	\$ 683.00	+
47	OUTSIDE TEMPRATURE SENSOR BRACKET <i>the new</i>	1	\$ 21.00	✓
48	CHAGRED AIR COOLER <i>Bent.</i>	1	\$ 654.00	?
49	CHARGED AIR COOLER PRESSURE HOSE - LH <i>the new</i>	1	\$ 496.00	+
50	RADIATOR <i>the new</i>	1	\$ 699.00	+
51	RADIATOR COOLANT <i>the new</i>	6	\$ 282.00	+
52	RADIATOR AIR GUIDE OUTER - LH / RH <i>LH Defend</i>	2	\$ 102.00	51
53	RADIATOR AIR GUIDE INNER - LH / RH <i>RH Defend</i>	2	\$ 38.00	19.
54	RADIATOR AIR GUIDE UPPER <i>the new</i>	1	\$ 19.00	+
55	FRONT NO PLATE <i>Bent</i>	S/N	\$ 60.00	✓
56	SUNDRIES <i>the new</i>		\$ 400.00	90.24.
TOTAL SPARE PARTS			\$ 27,517.00	
TOTAL LABOUR CHARGES			\$ 12,452.00	
GRAND TOTAL			\$ 39,969.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES PTE LTD



55 UBI ROAD 1, SINGAPORE 408094

TEL: 6596 2320 FAX: 6541 1183

PAGE 1/1

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Adrian L
16/02/22

Not Authorised, 04 Days (Without lode carrier)
07 Days (With lode carrier).

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

06 Days
S/S

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: