



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22001539/Uvf3e2 Date: 21/03/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKP 6911S
	Policy No.	Z21VP05029081	Coverage (\$)	0.00
	Claim No.	21/22/22/VP05/025468	Excess (\$)	1,000.00
	Assign From	GERALD POH	Assign Date	17/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C 180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WDD2040312A841590	Colour	BLACK
	Odometer	139454 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	PIRELLI	7 mm
	L/H Front Tyre	225/45 R17	PIRELLI	7 mm
	R/H Rear Tyre	225/45 R17	PIRELLI	7 mm
	L/H Rear Tyre	225/45 R17	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/02/2022	Inspection Date	17/02/2022
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A)THE MARKET VALUE IS S\$35,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	