Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

Ltd.

4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Fievel Foo Wenyao Date: 01 Jun 2022

Preliminary Advice

Insured : GBG5242A

Vehicle No

TP Vehicle Accident Date : SBK45P : 11/02/2022

No

Assignment Date: 17/02/2022 Make : VOLKSWAGEN ARTEON

Date of : 18/02/2022 Est. Duration of · 4

Inspection Repair

Inspection At: ALAN'S UNITED AUTO PTE LTD (HQ)

BLK 7 SIN MING INDUSTRIAL ESTATE, #01-76

SINGAPORE 575642

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 9,725.90 **Revised Amount** :S\$ 7,600.30 Check Items (Estimated) :S\$ 1,286.28 Total :S\$ 8,886.58

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

:S\$ 100,000.00 Pre-Accident Value COE / PARF Rebate :S\$ 71,048.00 Salvage Value :S\$

Margin for Repair :S\$ 28,952.00

Remarks

()	The vehicle is economical for repair
()	The vehicle is not economical for repair
()	Part-by-Part repair
()	Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.