

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000591**

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SMD7216Z
WONG ZUNG EN (HUANG SONG'EN)
 25 TAMPINES CENTRAL 7
 #14-29
 SINGAPORE,
 SINGAPORE 528610
 CONTACT NO : 93633648

DATE : 19-FEB-2022
 MAKE : TOYOTA
 MODEL : SIENTA STANDARD (AUTO)
 CHASSIS NO : MHFZ28H3300056260
 ENGINE NO : 2NRX356932
 SERVICE ADVISOR : HAZEL
 PAGE : 1 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	TAIL GATE	1,117.85	Xr
1	TAILGATE LOCK	276.27	XsVC
1	TAILGATE CATCH	45.00	XsVC
1	TAILGATE INNER TRIM	179.49	XsVC
1	TAILGATE INNER TRIM HANDLE	68.33	XsVC
1	TAILGATE HINGE RH	55.62	XsVC
1	TAILGATE HINGE LH	55.62	XsVC
1	TAILGATE DAMPER RH	239.70	XsVC
1	TAILGATE DAMPER LH	239.70	XsVC
1	TAILGATE EMBLEM LOGO "TOYOTA"	79.00	/MrC
1	TAILGATE EMBLEM "SIENTA"	87.80	/Nee
1	TAILGATE OUTER CHROME MOULDING	236.23	XsVC
1	TAILGATE WEATHER STRIP	255.20	XsVC
1	TAIL LAMP RH	358.70	XsVC
1	TAIL LAMP LH	358.70	XsVC
1	TAILGATE LAMP RH	199.50	XsVC
1	TAILGATE LAMP LH	199.50	XsVC
1	REAR CORNER PANEL RH	720.50	/DT 5864 288 302
1	REAR CORNER PANEL LH	720.50	XsVC
1	REAR BUMPER	337.50	Cut
1	REAR BUMPER DIFUSSER	198.90	XsVC
1	REAR BUMPER REFLECTOR RH	67.60	91 / Scr
1	REAR BUMPER REFLECTOR LH	67.60	XsVC
1	REAR BUMPER CENTRE REFLECTOR	62.50	XsVC
1	REAR BUMPER SIDE RETAINER RH	87.60	XsVC
1	REAR BUMPER SIDE RETAINER LH	87.60	XsVC
1	REAR END PANEL OUTER	359.22	7 Xr

310

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000591**

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

ATTN : MOTOR CLAIM DEPARTMENT

SMD7216Z

WONG ZUNG EN (HUANG SONG'EN)

25 TAMPINES CENTRAL 7

#14-29

SINGAPORE,

SINGAPORE 528610

CONTACT NO : 93633648

DATE : 19-FEB-2022
 MAKE : TOYOTA
 MODEL : SIENTA STANDARD (AUTO)
 CHASSIS NO : MHFZ28H3300056260
 ENGINE NO : 2NRX356932
 SERVICE ADVISOR : HAZEL
 PAGE : 2 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REAR END PANEL INNER	595.03 ? Xv	
1	REAR END PANEL TOP GARNISH	158.00 XSVc	
1	FLOOR PANEL	950.00 ? Xv	
Sub Total		8,464.76	0.00

~~638.93~~
655.43

SPECIAL NETT

10	REAR BUMPER CLIPS	50.00 30neC	
1	TAILGATE SEALANT	50.00 XNN	
1	WINDSCREEN SEALANT	50.00 XNN	
2	REAR BUMPER SENSOR	720.00 / cut 200	
1	REVERSE CAMERA	380.00 ^ XSVc	
1	REAR END PANEL SEALANT	50.00 ? XNN	
1	REAR NUMBER PLATE WITH BRACKET	60.00 XSVc	260
10	REAR END PANEL TOP GARNISH CLIPS	50.00 30	
Sub Total		1,410.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,600.00 400
1	TO SPRAY PAINT ON AFFECTED AREAS	1,600.00 400
1	TO REMOVE AND REFIX REAR WINDSCREEN	120.00 XNN
1	TO APPLY TUFF COAT ON AFFECTED AREAS	150.00 30

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4

#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809

Tel: 67139400 Fax: 67139415

Email: servicecentre@abwinm9.com Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000591****TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.****ATTN : MOTOR CLAIM DEPARTMENT****SMD7216Z****WONG ZUNG EN (HUANG SONG'EN)**

25 TAMPINES CENTRAL 7

#14-29

SINGAPORE,

SINGAPORE 528610

CONTACT NO : 93633648

DATE	:	19-FEB-2022
MAKE	:	TOYOTA
MODEL	:	SIENTA STANDARD (AUTO)
CHASSIS NO	:	MHFZ28H3300056260
ENGINE NO	:	2NRX356932
SERVICE ADVISOR	:	HAZEL
PAGE	:	3 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO DISMANTLE, REPLACE AND/OR REPAIR TAILGATE COMPONENTS	150.00	XNN
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	150.00	30
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	200.00	XNN
Sub Total		3,970.00	0.00

Thevan@LHhauto.com

82235769

3/3/22

1230

L/S after repair photo

F. 1450
RD. 3**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUB-TOTAL	13,844.76	0.00
GST - 7 %	969.13	0.00
TOTAL	14,813.89	0.00

ABWIN SERVICE PTE LTD

Prepared By