

ESTIMATE

Invoice Name & Address				Owner Name & Vehicle Info			
SALES DEPARTMENT (PDI EXPENSE)-MIT				Cust No/Name	B1000001/CYCLE & CARRIAGE LEASING PTE LT		
MIT USED CAR MAINT COST				Reg No/Reg Date	SML3614S / 07/10/201		
				Date In/Mileage	/ 0		
				Chassis No	JHMRU1810GX200289		
				Engine No/Capacity	L15B4530288 1496		
				Model/Description	HONDA /HRV 1.5 DX CVT		
Contact No				Colour/Trim	BEIGE /		
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
B1000001	Internal	11/02/2022/ 08:51	TLK	282 / Kevin Leong	40048		
Description of Goods / Services					Qty	Unit Price	Disc% Amount
E PNT88000							600 2560.00
REPLACE REAR BUMPER, TAILGATE & AFFECTED AREA 399 x 2							
REPAIR ON END PANEL							250 500 1650.00
E PNT98000							40 150.00
PAINT WORK ON REAR TAILGATE & END PANEL 250 x 1							150 300.00
E PNT88000							50 100.00
REMOVE & INSTALL REAR PARKING ASSISTS							30 80.00
E PNT88000							X 80.00
REMOVE & INSTALL REAR WINDSCREEN FOR FACILITATE REPAIR							
M SUNDRY							120.00
TO APPLY WINDSCREEN SEALANT							300.00
M SUNDRY							
TO APPLY SEALANT ON AFFECTED AREA							
M SUNDRY							
PERFORM RUST PREVENTION							
I 54900099							
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
I 10028901							
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							20 50.00
SUNDRIES							
M SUNDRY							730.08 912.60 1068.00
REAR BOOT PANEL / 00							663.2 829.00
M SUNDRY							
REAR BUMPER / CRU							net 35.00
M SUNDRY							net 35.00
EMBLEM 'I-VTEC' / REC							
M SUNDRY							25.00
EMBLEM 'HR-V' / REC							
M SUNDRY							
HONDA PLATE X NN							980.00
M SUNDRY							
WINDSHIELD GLASS RR X NN							

Confirm & accepted by

P-1741.60
-20%
1393.28

N-146 L-1260

Supp-25

Authorized signatory and company stamp

P/P - 2824.28

STIMATE

ESTIMATE

Invoice Name & Address				Owner Name & Vehicle Info				
SALES DEPARTMENT (PDI EXPENSE)-MIT MIT USED CAR MAINT COST Contact No				Cust No/Name	B1000001/CYCLE & CARRIAGE LEASING PTE LT			
				Reg No/Reg Date	SML36145 / 07/10/201			
				Date In/Mileage	/ 0			
				Chassis No	JHMRU1810GX200289			
				Engine No/Capacity	L15B4530288 1496			
				Model/Description	HONDA /HRV 1.5 DX CVT			
				Colour/Trim	BEIGE /			
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
B1000001	Internal	11/02/2022/ 08:51	TLK	282 / Kevin Leong	40048			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY WINDSHIELD GLASS MOUNTING / nec								76.00

Estimate

Steve (LKK)
13/4/22, 1-3pm

ML
P/P
by AL
4 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

Parts	0.00
Labour	5,080.00
Standard Menu	0.00
Specialist Job	0.00
Others(Lub,etc)	0.00
Sundry	3,358.00
Total(w/o GST)	8,438.00