

Surveyor : STEVE  
Claim : TP (CHINA TAIPIING)  
DOA : 30/12/2021  
Emailed : \_\_\_\_\_  
Date Survey : 13/04/2022

VEHICLE NO : SML3614S  
MODEL : HONDA / HRV 1.5 DX CVT  
WIP : 40048

|                  |   |                          |   |
|------------------|---|--------------------------|---|
| Material         | : | <u>2,093.00</u>          |   |
| Labour           | : | <u>1,260.00</u>          |   |
| Sub-Total        | : | <u>\$ 3,353.00</u>       | - |
|                  | : | <u>\$</u>                | - |
| Less Excess      | : | <u>\$</u>                | - |
| Total            | : | <u>\$ 3,353.00</u>       | - |
| GST 7%           | : | <u>\$ 234.71</u>         | - |
| Grand Total      | : | <u>\$ 3,587.71</u>       | - |
| Finalise By/Date | : | <u>LARRY ON 27/04/22</u> |   |

☒ REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 04 WORKING DAYS + 2 Days (ONE) Weekends  
+ \_\_\_\_\_ Days ( \_\_\_\_\_ ) Public Holiday  
TOTAL DAYS REPAIR TOOK = 06

☒ TP claim SJP6220P (CHINA TAIPIING)

☒ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others \_\_\_\_\_

☐ Third Party Report - \_\_\_\_\_

ESTIMATE

| Invoice Name & Address           |  | Owner Name & Vehicle Info |                                          |
|----------------------------------|--|---------------------------|------------------------------------------|
| CYCLE & CARRIAGE LEASING PTE LTD |  | Cust No/Name              | B1000001/CYCLE & CARRIAGE LEASING PTE LT |
| 239 Alexandra Road               |  | Reg No/Reg Date           | SML3614S / 07/10/201                     |
| Singapore 159930                 |  | Date In/Mileage           | 13/04/2022/ 224679                       |
|                                  |  | Chassis No                | JHMRU1810GX200289                        |
|                                  |  | Engine No/Capacity        | L15B4530288 1496                         |
| Contact No Mobile:               |  | Model/Description         | HONDA /HRV 1.5 DX CVT                    |
|                                  |  | Colour/Trim               | BEIGE /                                  |

| Account No | Terms | Date/Time Printed | CSE | Operator          | WIP No |
|------------|-------|-------------------|-----|-------------------|--------|
| IA100000   | Cash  | 27/04/2022/ 11:06 | TLK | 260 / Loi Ai Ting | 40048  |

| Description of Goods / Services |                                                            | Qty  | Unit Price | Disc% | Amount    |
|---------------------------------|------------------------------------------------------------|------|------------|-------|-----------|
| E                               | PNT88000                                                   |      |            |       | 600.00 ✓  |
|                                 | REPLACE REAR BUMPER, TAILGATE & AFFECTED AREAS             |      |            |       |           |
| E                               | PNT98000                                                   |      |            |       | 250.00 ✓  |
|                                 | PAINT WORK ON REAR TAILGATE                                |      |            |       |           |
| E                               | PNT88000                                                   |      |            |       | 40.00 ✓   |
|                                 | REMOVE & INSTALL REAR PARKING ASSIST                       |      |            |       |           |
| E                               | PNT88000                                                   |      |            |       | 150.00 ✓  |
|                                 | REMOVE & INSTALL REAR WINDSCREEN TO FACILITATE REPAIR      |      |            |       |           |
| M                               | SUNDRY                                                     |      |            |       | 50.00 ✓   |
|                                 | APPLY REAR WINDSCREEN SEALANT                              |      |            |       |           |
| M                               | SUNDRY                                                     |      |            |       | 30.00 ✓   |
|                                 | APPLY SEALANT ON AFFECTED AREAS                            |      |            |       |           |
| I                               | 10028901                                                   |      |            |       | 120.00 ✓  |
|                                 | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM |      |            |       |           |
| M                               | SUNDRY                                                     |      |            |       | 20.00 ✓   |
|                                 | SUNDRIES                                                   |      |            |       |           |
| X                               | TRUNK LID ✓                                                | 1.00 | 1068.00    | 0.00  | 1068.00 ✓ |
| X                               | RR BUMPER ✓                                                | 1.00 | 829.00     | 0.00  | 829.00 ✓  |
| X                               | RUBBER W/SHLD DAM → Supp                                   | 1.00 | 25.00      | 0.00  | 25.00 ✗   |
| X                               | MOULDING ASSY L FRT DOOR → Supp                            | 1.00 | 25.00      | 0.00  | 25.00 ✗   |
| X                               | MOULDING UP LWR ✓                                          | 2.00 | 38.00      | 0.00  | 76.00 ✓   |
| X                               | EMBLEM I-VTEC ✓                                            | 1.00 | 35.00      | 0.00  | 35.00 ✓   |
| X                               | EMBLEM HRV ✓                                               | 1.00 | 35.00      | 0.00  | 35.00 ✓   |
| Z                               | TEXT                                                       |      |            |       |           |
|                                 | TP CLAIM CHINA TAIPING - SJP6220P                          |      |            |       |           |
|                                 | DOA: 30/12/2021                                            |      |            |       |           |
|                                 | SURVEY: STEVE (LKK) 13/04/2022                             |      |            |       |           |
|                                 | 04 DAYS                                                    |      |            |       |           |

Confirm & accepted by

Authorized signatory and company stamp

Parts  
Labour  
Standard Menu  
Specialist Job  
Others (Lub, etc)  
Sundry  
Total (w/o GST)

3,353.00



INSURANCE CO. : CHINA TAIPING

Supplementary Parts For Registration No.: SML 3614 S

**Materials**

- 1 Rubber W/Shld Dam
- 2 Moulding Assy L Frt Door

**Cost (\$)**

|            |              |             |
|------------|--------------|-------------|
| <i>net</i> | 25.00        | <i>Nett</i> |
| <i>nn</i>  | 25.00        | <i>x</i>    |
|            | <u>50.00</u> |             |
|            | 3.50         |             |
|            | <u>53.50</u> |             |

7% Gst

**Total**

*25*  
*~~25%~~*  
*20*  
*1*

Thank You.

Yours faithfully  
REPUBLIC AUTO PTE LTD

Larry Songcuan  
Customer Service  
TEL: 6568 4658  
FAX : 6567 5258