



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22001548/Atf3n2	
			Date: 20/06/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBL 1768A	Veh. Inspected	SMM 9093A
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200618/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	17/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI AVANTE	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHD841CMLU965899	Colour	SILVER
	Odometer	44487 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	KUMHO	6 mm
	L/H Front Tyre	205/55 R16	KUMHO	6 mm
	R/H Rear Tyre	205/55 R16	KUMHO	6 mm
	L/H Rear Tyre	205/55 R16	KUMHO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/02/2022	Inspection Date	18/02/2022
	Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	