

CYCLE & CARRIAGE

TP - CHINA TAIPIING
SURVEY: 17/05/22
LKK - STEVE

VEHICLE NO : SMZ 2653L

MODEL : MIT/OUTLANDER 2.0 CVT

WIP : 20626

Material	:	\$	<u>2,463.00</u>
Labour	:	\$	<u>1,660.00</u>
Sub-Total	:	\$	<u>4,123.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>4,123.00</u>
GST 7%	:	\$	<u>288.61</u>
Grand Total	:	\$	<u>4,411.61</u>
Finalise By/Date : <u>Larry on 19/10/22</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS

* TP VEHICLE NO: YN3361T

* GLA SEARCH FEE \$200

* LOSS of USE.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
YAP CHONG HOW (YE ZHONGHAO)	Cust No/Name KCV19012/YAP CHONG HOW (YE ZHONGHAO)
BLK 585 ANG MO KIO AVENUE 3	Reg No/Reg Date SMZ2653L / 19/04/2021
#06-3039	Date In/Mileage 17/05/2022/ 9241
SINGAPORE 560585	Chassis/Package GF7W0701228 /#
Contact No Mobile: 92231102	Engine No 4J11DC4965
17/05/2022	Make/Model MIT/2OMY OUTLANDER 2.0 CVT MODERN (997)
	Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	19/10/2022/ 11:04	TLK	884 / Lauro Songcuan	20626

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER & AFFECTED AREAS				640.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				280.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY FRONT NUMBER PLATE WITH FRAME				50.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER				550.00 ?
X FACE,FR BUMPER ?	1.00	851.00	00.00	851.00 ?
X MARK,THREE-DIA ✓	1.00	72.00	00.00	72.00 ✓
X EXTENSION,FR BUMPER ?	1.00	509.00	00.00	509.00 ?
X COVER,FR BUMPER ✓	1.00	361.00	00.00	361.00 ✓
X CLIP,RR BUMPER	10.00	3.00	00.00	30.00 x
X CLIP,ENG ROOM COVER	20.00	2.00	00.00	40.00 x
X RIVET,FR BUMPER	10.00	5.00	00.00	50.00 x
X GRILLE ASSY,RADIATOR ✓	1.00	550.00	00.00	550.00 ✓
Z TEXT TP CLAIM CHINA TAIPING - YN3361T DOA: 06/02/2022 SURVEY: STEVE (LKK) 17/05/2022 03 DAYS				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	2,463.00	Nett	4,123.00
Labour	1,590.00	7% GST on	288.61
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	4,411.61
Diagnostics Job	0.00		
Sundry/Others	20.00		
Total(w/o GST)	4,123.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : CHINA TAIPING

Supplementary For Registration No.: SMZ 2653 L

		<u>Cost \$</u>	
<u>Materials</u>			
1	Clip, RR Bumper (10 pcs)	30.00 ✓	NEC
2	Clip, Eng Room Cover (20 pcs)	40.00 ✓	NEC
3	Rivet, FR Bumper (10 pcs)	50.00 ✓	NEC
		<u>120.00</u>	
7% Discount		<u>8.40</u>	
		<u>128.40</u>	

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SM2 2653LWIP: 20626 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1 ✓	FR BUMPER	? / SUPP		✓ CR	
2 ✓	Spray Paint FR Bumper \$400	? / SUPP	\$550/2	✓ M	Steve
3	Clip X 20 X upper Cover Clips 10 each	? / SUPP		✓ CUT	18/5/22
4	EXTENSION FR Bumper	? / SUPP		✓ M	
5	Repeat X 10	? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OutlanderSURVEYOR: Steve-LKH