



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YAP CHONG HOW (YE ZHONGHAO)	Cust No/Name KCV19012/YAP CHONG HOW (YE ZHONGHAO)
BLK 585 ANG MO KIO AVENUE 3	Reg No/Reg Date SMZ2653L / 19/04/202
#06-3039	Date In/Mileage / 0
SINGAPORE 560585	Chassis No GF7W0701228
Contact No	Engine No 4J110C4965
	Make/Model MIT/ZOMY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV19012	CRDVCH	11/02/2022/ 08:58	TLK	282 / Kevin Leong	20626
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT BUMPER & AFFECETED AREA				642 1280.00
E PNT98000	PAINT WORK ON FRT BUMPER PANEL ? 550			550 ✓ ?	550 1100.00
M SUNDRY	PERFORM RUST PREVENTION				X 80.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120.00 ✓
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				280.00 ✓
M SUNDRY	TO SUPPLY FRT NUMBER PLATE WITH FRAME				50.00 ✓
M SUNDRY	SUNDRIES ? CRU				20 50.00
M FACE,FR BUMPER	FACE,FR BUMPER ? CRA	1.00	851.00	00.00	851.00 ✓
M GRILLE ASSY,RADIATOR	GRILLE ASSY,RADIATOR ?	1.00	550.00	00.00	550.00 ✓
M MARK,THREE-DIA	MARK,THREE-DIA ?	1.00	72.00	00.00	72.00 ✓
M EXTENSION,FR BUMPER	EXTENSION,FR BUMPER ? CUT	1.00	509.00	00.00	509.00 ✓
M COVER,FR BUMPER	COVER,FR BUMPER ?	1.00	361.00	00.00	361.00 ✓
M REINFORCEMENT,FR BUMPER	REINFORCEMENT,FR BUMPER ? X NN	1.00	510.00	00.00	510.00 ✓
<p>Sten (CLKK)</p> <p>17/5/22, 2.2pm</p> <p>mm R</p> <p>P/P</p> <p>M R</p> <p>3 L</p>					
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Authorized signatory and company stamp</p>					
<p>Confirm & accepted by</p>					
<p>7% GST on</p>					
<p>Nett</p>					5,813.00
<p>Total Payable</p>					6,219.91

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.