



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
YAP CHONG HOW (YE ZHONGHAO)  BLK 585 ANG MO KIO AVENUE 3 #06-3039 SINGAPORE 560585  Contact No	Cust No/Name	KCV19012/YAP CHONG HOW (YE ZHONGHAO)
	Reg No/Reg Date	SMZ2653L / 19/04/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0701228
	Engine No	4J11DC4965
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV19012	CRDVCH	11/02/2022/ 08:58	TLK	282 / Kevin Leong	20626			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E	PNT88000							1280.00
	REPLACE FRT BUMPER & AFFECETED AREA							
E	PNT98000							1100.00
	PAINT WORK ON FRT BUMPER PANEL							
M	SUNDRY							80.00
	PERFORM RUST PREVENTION							
A	54900099							120.00
	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A	10028901							280.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M	SUNDRY							50.00
	TO SUPPLY FRT NUMBER PLATE WITH FRAME							
M	SUNDRY							50.00
	SUNDRIES							
M	FACE,FR BUMPER				1.00	851.00 00.00	851.00	
M	GRILLE ASSY,RADIATOR				1.00	550.00 00.00	550.00	
M	MARK,THREE-DIA				1.00	72.00 00.00	72.00	
M	EXTENSION,FR BUMPER				1.00	509.00 00.00	509.00	
M	COVER,FR BUMPER				1.00	361.00 00.00	361.00	
M	REINFORCEMENT,FR BUMPER				1.00	510.00 00.00	510.00	

Confirm &amp; accepted by

	<b>Nett</b>	<b>5,813.00</b>
7% GST on	<b>5813.00</b>	<b>406.91</b>
<b>Total Payable</b>		<b>6,219.91</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.