



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001550/Eqf3e2	
			Date: 30/03/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 3263T	Veh. Inspected	SLR 9606G
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000466MFCV/PTE/CL	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	17/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ESTIMA	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	ACR507137995	Colour	GREY
	Odometer	74831 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R18	BRIDGESTONE	5 mm
	L/H Front Tyre	225/50 R18	BRIDGESTONE	5 mm
	R/H Rear Tyre	225/50 R18	BRIDGESTONE	5 mm
	L/H Rear Tyre	225/50 R18	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/02/2022	Inspection Date	01/03/2022
	Survey held at	SHU FATT AUTO WORKS BLK 1009,BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	