



樹發汽車修理廠 SHU FATT AUTO WORKS

0-16

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-quo

18th February 2022

MS First Capital- TP

SLR 9606 G TOYOTA ESTIMA

Spare Parts			SS	
1	Rear boot.	DP	1853.60	1635
1	Rear boot logo.	AKC	72.20	
1	Rear boot 'Estima' emblem.	AKC	75.70	
1	Rt rear boot inner stopper.	X AN	29.80	
1	Rear windscreen moulding.	AKC	110.60	
1	Rt rear boot reflector.	OR	784.90	
1	Rt rear tail light.	OR	667.00	
1	Rear bumper.	X R	622.10	
1	Set rear bumper clips.	X AN	66.00	
2	Rear bumper side retainers.	@\$67.70 X AN	135.40	
2	Rear bumper sensors.	@\$310.90 X AN	621.80	
1	Rear windscreen inner seal.	AKC	42.00	Snet
1	Rear windscreen sealant.	AKC	55.00	Snet
			5136.10	
		Less 25%	1259.77	
			3876.33	
Labour	To knock, straighten rear support panel, rear inner panel, rear lower panel, rear side panel, rt rear fender, rt rear fender inner panel, rt rear floor board, renew rear boot, rear reflector, rear lights, rear bumper and assembly.		1200.00	500
	To respray damaged parts.		1200.00	600
	To remove, replace rear windscreen.		180.00	120
	To remove rear garnishes, carpets, upholstery, rear seats, side covers to facilitate repairs and assembly.		280.00	50
	To remove, replace, transfer rear boot inner lock, outer lock, inner motors, rubbers, mouldings and assembly.		150.00	50
	To reseal joints, reinsulate, anti rust panels and assembly.		120.00	30
			7006.33	

Bridgestone 225/50R18
ACR50- 7137995

Steve (LKK)

1/3/22, 10.00am

83228813

Stenckm@lkkauto.com

mm PL

L/S

ly AL sy

4 dys

1350
=3979.05
L/S-3143.24
=3150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: