

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

VFM PTE LTD
c/o 46 Lentor Plain
Singapore 786548

Not Notarised
11/12/22
Recovery After Repair
3 days

Date: 17/2/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
	HONDA VEZEL/ SLP 5446 M	
	HYBRID	
1 pc	Tailgate badge - logo X	
1 pc	Tailgate "VEZEL" emblem ✓	
1 pc	Tailgate "HYBRID" emblem ✓	
1 pc	Rear Bumper ✓	
1 set	Rear bumper reflectors ✓	
	sub-total	
1 set	Reverse sensor	
	s.nett <i>2000</i>	<i>\$250.00</i>
	sub-total	
	Labour charges to repair, panel beat and straighten damaged parts and replace the above mentioned parts.	<i>2200</i> <i>\$300.00</i>
	To replace reverse sensor and check wiring functions.	<i>\$ 70.00</i> <i>500</i>
	To putty, apply primer & spray paint the affected areas.	<i>4200</i> <i>\$ 500.00</i>
	sub-total	
	Total	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: Page 1 of 1