

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

VFM PTE LTD

c/o 46 Lentor Plain
Singapore 786548

*Not withash
11/12/2022 @ 1300hr
Putty After Pain
3 days*

Date: 17/2/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
	HONDA VEZEL/ SLP 5446 M	
	HYBRID	
1 pc	Tailgate badge - logo X	62.80 NN
1 pc	Tailgate "VEZEL" emblem =	67.50 Nec
1 pc	Tailgate "HYBRID" emblem =	78.30 Nec
1 pc	Rear Bumper ✓	957.20 Def
1 set	Rear bumper reflectors ✓	89.80 Cut
		762.0
	sub-total	
1 set	Reverse sensor	shut s.nett 2000 ✓ \$250.00
	sub-total	
	Labour charges to repair, panel beat and straighten damaged parts and replace the above mentioned parts.	224 \$300.00
	To replace reverse sensor and check wiring functions.	\$ 70.00 500
	To putty, apply primer & spray paint the affected areas.	424 \$ 500.00
	sub-total	
	Total	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company