

E NO SHD4129X

03/02/22

REG .22.10.2022

CHIANG/NTUC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET LH / RH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$111.60
2	REAR BUMPER REINFORCEMENT STAY LH/RH		\$394.80
1	REAR BUMPER CENTRE MOULDING		\$138.10
1	REAR BUMPER TOW COVER		\$276.20
1	REAR BUMPER FOG LAMP		\$451.25
2	REAR NUMBER PLATE LAMP		\$94.60
2	REAR BUMPER REFLECTOR LH / RH		\$201.50
10	REAR BUMPER CLIPS		\$85.30
			\$41.45
			\$170.60
			\$2.20
			\$82.90
			\$22.00
			\$2,264.85
			\$452.97
			\$1,811.88
			\$200.00
			\$50.00
			\$180.00
			\$55.00
			\$461.50
			\$500.00
			\$300.00
			\$60.00
			\$60.00
			\$60.00
			\$980.00
			\$3,253.38

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan

8223 5769

4/2/22 10/5

US after repair photo
2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: