

Our Job Ref No : 305503597

Date : 12/02/22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6540 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHD4129X

03/02/22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2 The repair job shall bill to: NTUC FBN5748X

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$1,500.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name :

Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

E NO SHD4129X

03/02/22

KE REG .22.10.2022

CHIANG/NTUC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET LH / RH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$394.80
2	REAR BUMPER REINFORCEMENT STAY LH/RH		\$138.10
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER TOW COVER		\$94.60
1	REAR BUMPER FOG LAMP		\$201.50
2	REAR NUMBER PLATE LAMP		\$85.30
2	REAR BUMPER REFLECTOR LH / RH		\$41.45
10	REAR BUMPER CLIPS		\$2.20
	SUB TOTAL		\$2,264.85
	20.00%		\$452.97
	DISCOUNTED TOTAL		\$1,811.88
2	REAR FENDER ADVERTISEMENT LH/RH		\$200.00
1	REAR BUMPER MAT		\$50.00
1	REAR REVERSE SENSOR		\$180.00
1	REAR BUMPER NUMBER PLAT W/HOLDER		\$55.00
	Labour Charge		
	Panel Beating		\$500.00
	Spray Painting Charge		\$300.00
	Check Lighting and Wiring		\$60.00
	Tuff Kote		\$60.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$980.00
	ESTIMATE TOTAL		\$3,253.38

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thum

8223 5769

4/2/22 10/5

LS after repair photo
2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: