

Our Job Ref No : 30550341 Date : 12/02/22					ENGINEERING ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508989						
Fax: 6546 8156											
То	:		LKK		Fax:						
	. —		THEWAN								
Attn	la Dag	No. : SHA5				29.01.2022					
			,								
The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-											
Z	Z The repair job shall bill to:					SJQ5050P					
2.	The fir	nalized amount s	hall be:								
	(a)	Spare Parts afte									
		I - h Oh									
	(b)	Labour Charges	y-Part Repair Cost								
		Total for Part-b	y-rait Kepan oost								
	(c.)	Lumpsum Repa	r (if applicable)								
		Total for Lumpsum	um repair cost after Less: Repair cost		•	\$2,250.00					
3.	Estimated normal period for repairs: working days.										
4.	We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7										
	working days										
5. Thank you for your assist			istance.		We confirm the estimates and finalized amount						
						α					
				Signature:							
	Signa	ture :		Sig	nature:						
Name : CHIANG				Na	me :						
Tel : <u>62148314</u>				Da	te :						
	Fax : 65468156										
For C	fficial	Use Only									
				Document	Confirm By	5					
	Item		Amount	Attached Yes or No	(Signature)	Remarks					
1. Re	Rental Rate P/Day			YES							
	Loss of Income Paid		3 - 7	Ŋ							
3. St	Survey Fees										
4. LTA Search Fee		ch Fee	\$7.49/\$2.00								
Medical Fees (on behalf of driver, if applicable)		ees (on behalf if applicable)									
6 O	errun										
Rema	ırks:										

RTDEL ENGINEERING PTE LTD CO

REPAIR ESTIMATE*

VEHICLE NO

SHA5758P

MAKE

REG 12.05.2016

DATE 29/01/2022 CHIANG /NTUC

MODEL

HVII. MO

MODEL	HYU- 140	_	Unit Price	Amount		
Qty	Parts Description/ Labour	Туре	I Onit Frice		* CUC	
				\$1,388.00 \$663.00 \$174.90	7, 7, 7, 7	
	1 HEADLAMP LH			\$663.00	n/1)	
	1 FENDER LH			\$174.90	7, XSVL	
	1 FENDER SHIELD LH			\$14.30	nie	
	1 FRONT BUMPER SIDE RH /LH			\$24.60	-N2C	
	1 FRONT BUMPER BRACKET LH/RH			\$187.20		
1	1 FRONT BUMPER GRILLE LH			\$1,052.20		
1	1 FRONT BUMPER ASSY			\$907.40	T. KSUC	
1	1 HEADLAMP SUPPORT PANEL			\$715.00		
1	1 LH ROCKER GARNISH			\$214.20		
	1 WHEEL HUB COVER			\$5,340.80	,	
	SUB TOTAL			\$1,068.16		
	20.00%			\$4,272.64		
	DISCOUNTED TOTAL			\$4,272.01		
	507 707 811			\$216.00	5V2 >	
1	1 FRT TYRE RH			\$75.00	NOC	
1	FRT DOOR LOGO STICKER FRT DOOR COMFORTDELGRO STICKER			\$75.00	NAC	
1	FRI DOOR CONFORTBELGRO STICKER			\$329.40		
1		1				
	Labour Charge					
	Panel Beating			\$700.00	560	
	Spray Painting Charge			\$1,000.00	00	
	Check wiring		·	\$60.00	20	
	Tuff kote			\$60.00	ZO	
	TOTAL LABOUR			\$1,820.00		
	ESTIMATE TOTAL	1		\$6,422.04		
			ĺ			
				1		
				1		
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will					

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theran 82235769 4/2/21 1600 LIS after varyain photo WP 3clays Z

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: