COMFORTDELGRO

Our Job Ref No : 305503549					ENGINEERING							
Date		;	12/02/22		ComfortDolGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156							
FINA	LIZAT	ION FORM										
To	: _		LKK	-	Fax:							
Attn	:		THEVAN	-								
Vehi	cle Re	No. : SHC	7144L			03/02/22						
			the repairs of the above-me	entioned vehicle	e are as follow	s:-						
1116	The survey and estimates of the repeated					SJG8062M						
Z	The repair job shall bill to:			NTUC		300002111						
2.	The	finalized amount :	shall be:									
	(a)	Spare Parts aft	er List discount									
	(b)	Labour Charge:	S									
		Total for Part-l	By-Part Repair Cost									
	(c.)	Lumpsum Repa Total for Lumps	ir (if applicable) um repair cost after Less:	Spanning successive and	_							
		Final Lumpsur		\$3,000.0								
3. Estimated normal period for repairs: 3 working days.												
4.	 We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 											
5.	Thank	k you for your ass	istance	W	We confirm the estimates and							
0.	THAIR	k you lot your ass			finalized amount							
	Ciano	furo:		Sir	Signature :							
	Signa Name	-			Name :							
	Tel : 62148314				Date :							
	Fax	: 6546815										
For O	fficial	Use Only			,							
	ltem		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks						
Rental Rate P/Day				YES								
Loss of Income Paid			•	N								
3. Survey Fees		ees		<u> </u>								
4. LTA Search Fee			\$7.49/\$2.00	-								
Medical Fees (on behalf of driver, if applicable)					14							
6 Ov	errun				Ļ	· · · · · · · · · · · · · · · · · · ·						
Remai	rks:											

REPATT STIMATE

VEHICLE NO

5HC7144L

MAKE

REG. 28.04.2016

03/02/22

ODEL	1-40	CHIANG /NTUC			
Qty	Parts Description/ Labour	Type	Unit Price	Amount	/4
	LERONT BUMPER BRACKET LH			\$24.60/	11
	1 FRONT BUMPER TOP BRACKET LH			\$22.40/	7
	1 FRONT BUMPER			\$1,052.20	t
	1 FRONT BUMPER GRILLE / LH			\$93.45	
	1 FRONT FENDER LH			\$663.00	-0
	1 FRONT FENDER SHIFLD LH			\$174.90	1
	THEAD LAMP SUPPORT PANEL			\$907.40	7
	1 HEAD LAMP ASSY LH	- 1		\$1,388.00	15
3	DBUMPER CLIPS	- 1	\$2.20	\$22.00	n
	SUB TOTAL		[\$4,347.95	
	LESS 20%	1	[\$869.59	
		1	[\$3,478.36	
			[
			[
				1	
	Labour Charge				
	Panel Beating		1	\$600.00	
	Spray Painting Charge			\$600.00 5	
	Tuff Kote	3		\$60.00	2
	Check Lighting			\$60.00	LC
	TOTAL LABOUR		-	\$1,320.00	
	ESTIMATE TOTAL			\$4,798.36	
		1			
	-				
	· ·				

The van 82235769 U/2/22 1700 U/S 9 Har repair photo 30/945 wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer