

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Luyang Drive Singapore 608969  
Fax: 6546 8156

Our Job Ref No : 305503590  
Date : 12/02/22

## FINALIZATION FORM

To : LKK  
Attn : THEVAN  
Vehicle Reg No. : SHB4377G

Fax :

03/02/22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SMY8524S

2. The finalized amount shall be:

(a) Spare Parts after List discount \_\_\_\_\_

(b) Labour Charges \_\_\_\_\_

**Total for Part-By-Part Repair Cost** \_\_\_\_\_

(c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \$2,000.00

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :  \_\_\_\_\_

Signature :  \_\_\_\_\_

Name : CHIANG

Name : \_\_\_\_\_

Tel : 62148314

Date : \_\_\_\_\_

Fax : 65468156

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

COMFORTDELGRO PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO SHB4377G

03/02/22

MAKE REG. 20.12.2017

MODEL I-40

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET RH			\$24.60 <i>NA</i>
1	FRONT BUMPER TOP BRACKET RH			\$22.40 <i>NA</i>
1	FRONT BUMPER			\$1,052.20 <i>DT</i>
1	FRONT BUMPER GRILLE / RH			\$93.45 <i>XSUC</i>
1	FRONT FENDER RH			\$663.00 <i>DT</i>
1	FRONT FENDER SHIELD RH			\$174.90 <i>XSUC</i>
1	HEAD LAMP SUPPORT PANEL			\$907.40 <i>1. XSUC</i>
1	HEAD LAMP ASSY RH			\$1,388.00 <i>1. XSUC</i>
10	BUMPER CLIPS		\$2.20	\$22.00 <i>NA</i>
	<b>SUB TOTAL</b>			<b>\$4,347.95</b>
	<b>LESS 20%</b>			<b>\$869.59</b>
				<b>\$3,478.36</b>
	<b>Labour Charge</b>			
	Panel Beating			\$600.00 <i>560</i>
	Spray Painting Charge			\$600.00 <i>500</i>
	Tuff Kote			\$60.00 <i>20</i>
	Check Lighting			\$60.00 <i>20</i>
	<b>TOTAL LABOUR</b>			<b>\$1,320.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$4,798.36</b>

Thuan  
 82235769  
 4/12/22  
 1645  
 LIS after repair photo  
 3days wp

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer