Our	Job Re	ef No		305503540		COMFORTDELGRO ENGINEERING ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 6156				
Date	9			12/02/22						
To	ALIZAT		ORW	LKK		Fax;				
Attn	:			THEVAN						
		g No.	: SHA	7237M			31.01.2022			
The	survev	and es	stimates of	the repairs of the above-me	entioned vehicle	are as follows	i-			
Z			ob shall bi		NTUC		SJG6722E			
2.	The	finalize	d amount	shall be:						
	(a)	Spar	e Parts aft	er List discount						
	(b)	Labo	ur Charge	s						
		Tota	l for Part-	By-Part Repair Cost						
	(c.)	Total	for Lumps	air (if applicable) sum repair cost after Less; n Repai r cost	-		\$1,650.00			
3.4.5.	We s work	hall tre	at the abo		working days. and Confirmed if there is no reply from you within 7 We confirm the estimates and finalized amount					
	Signa	ture :		00	_	nature:				
	Name	:	CHIANG			me :	y ·			
	Tel	:	6214831	4	Da	ie ,				
	Fax	:	6546815	6	_					
For O	fficial	Use O	nly							
	ı	tem		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks			
	Rental Rate P/Day				YES					
	ntal Ra			-	N					
	vey Fe		3.0		•					
1 TA	A Sear	ch Fee		\$7.49/\$2.00						
Mar	dical F	ees (or	n behalf							
	lriver, it errun	applic	aule)							
Remark	ks:									

ORTDELGRO ENGINEERING PTE LTD

REP STIMATE*

VEHICLE NO

SHA7237M

REG .07.11.2019

04/01/22

CHIANG/NTUC

MAKE MODEL

IONIQ G3

IONIQ G3			_		
y Part	s Description/ Labour	Туре		Amount	
1 REAR BUMPER				\$459.4	
2 REAR BUMPER SI	DE BRACKET LH / RH		\$55.80		
1 REAR BUMPER RE	INFORCEMENT			\$394.8 \$276.2	
2 REAR BUMPER RE	INFORCEMENT STAY LH/RH		\$138.10	\$276.2	
1 REAR BUMPER CE	NTRE MOULDING			\$451.2	
1 REAR BUMPER TO	W COVER			\$94.6	
1 REAR BUMPER FO	G LAMP			\$201.50	
2 REAR NUMBER PL	ATE LAMP		\$85.30	\$170.60	
2 REAR BUMPER REI	FLECTOR LH /(H)		\$41.45		
10 REAR BUMPER CLI			\$2.20	\$22.00	
	SUB TOTAL	-		\$2,264.85	
	20.00%			\$452.97	
	DISCOUNTED TOTAL			\$1,811.88	
1 REAR REVERSE SENS	SOR			\$180.00	
1 REAR BUMPER NUM	IBER PLAT W/HOLDER			\$55.00	
		10.00%		\$211.50	
Labour Charge					
Panel Beating				\$500.00	
Spray Painting Charg	e			\$300.00	
Check Lighting and W	/iring			\$60.00	
Tuff Kote				\$60.00	
Remove/refix Reverse	esensor			\$60.00	
	TOTAL LABOUR			\$980.00	
	ESTIMATE TOTAL		\$3,003.38		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan 82235769 4/2/27 1730 Us after repair photo Zolays up

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Dale: