

Our Job Ref No : 305503542

Date : 12/02/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHC7314M

01/02/22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: NTUC SMK2581P

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$3,500.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name :

Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC7314M

03/02/22

MAKE 15/09/2016

MODEL HYU- I40

CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REFLECTOR LH /RH		\$32.00	\$64.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
1	REAR END PANEL			\$495.50
1	REAR PANEL GARNISH			\$57.70
1	BOOTLID			\$2,609.80
1	BOOTLID LOWER GARNISH			\$227.90
2	BOOTLID HINGES LH/RH		\$142.30	\$284.60
1	BOOTLID MOULDING			\$85.00
1	BOOTLID CDRI			\$52.40
1	BOOTLID EMBLEM I40			\$67.90
				\$5,247.40
				20.00%
				\$1,003.90
				DISCOUNTED TOTAL
				\$4,015.60
1	BOTLID CITYAB & TEL NO. STICKER			\$60.00
1	REAR BUMPER MAT			\$50.00
1	REVERSE SENSOR			\$135.70
				\$304.43
	Labour Charge			
	Panel Beating			\$750.00
	Spray Painting Charge			\$600.00
	Remove/refix reverse sensor			\$60.00
	Check lighting			\$60.00
	Tuff Kote			\$90.00
				\$1,560.00
				TOTAL LABOUR
				\$5,880.03
				ESTIMATE TOTAL

This is an initial estimate based on a visual inspection of the above vehicle. The final repair estimate will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance Company.

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thevan
82235769
4/2/22 1715
L/S after repair photo
3 days wp