



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/CTI21007541/Ety3-1

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Ref: ~~CS3/CTI21007541/c~~
Date: ~~12/07/2021~~ 18/02/2022
Code: CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJC 5928G	Veh. Inspected	SMA 8533S
Policy No.		Coverage (\$)	0.00
Claim No.	SNM21D203840/C02/SJC5928 G/TAYHP	Excess (\$)	0.00
Assign From	IRENE TAY	Assign Date	12/07/2021 18/02/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/07/2021	Inspection Date	12/07/2021
Survey held at	7 SOON LEE STREET #01-39 iSPACE S627608		
Repairer	LYS ENGINEERING		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.