



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : Z21VP05029372
Accident Date : 16-Feb-2022

No. : 32222

Date : 18-Feb-2022

Our Ref : 021645 / SANDRA

PAGE : 1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

ESTIMATED COST OF REPAIR FOR TOYOTA FORTUNER 2WD (2694CC)(2013) SML9008C

1 pc	front bumper		240.00 c
2 pcs	front bumper side retainer (LH&RH)	@ S\$ 35.00	70.00 c
10 pcs	front bumper clips	@ S\$ 1.50	15.00 c
1 pc	RH front bumper foglamp		135.00 c
1 pc	RH front bumper foglamp cover		55.00 c
1 pc	front bumper lower centre grille		130.00 c
1 pc	RH front bumper side mounting bracket		35.00 c
1 pc	RH front bumper retainer bracket		40.00 c
1 pc	front bumper reinforcement		120.00 c
1 pc	RH front bumper reinforcement bracket		35.00 c
1 pc	front grille		295.00 c
1 pc	front grille bracket		200.00 c
10 pcs	front grille clips	@ S\$ 1.50	15.00 c
1 pc	front grille logo		55.00 c
1 pc	front grille top seal		45.00 c
1 pc	RH front fender		195.00 c
1 pc	RH front fender inner shield		145.00 c
10 pcs	RH front fender inner shield clips	@ S\$ 1.50	15.00 c
1 pc	RH front fender wheel arch garnish		200.00 c
1 pc	RH front fender wheel arch garnish top moulding	—no stock	

Con't Page 2 ...

Press any key to continue..

CO. REG. NO: 199402370D
GST NO: M2-0123250-3



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : Z21VP05029372
Our Ref : 021645

Page : 2
No. : 32222

1 pc	RH headlamp panel and front support panel	295.00	c
1 pc	front bumper under cover	150.00	c
10 pcs	front bumper under cover clips @ S\$ 1.50	15.00	c
1 pc	RH headlamp	350.00	c
1 pc	air pump	750.00	c
1 pc	air pump bracket	135.00	c
1 pc	air pump cover	115.00	c
1 pc	RH front shock absorber	125.00	c
1 pc	RH front shock absorber mounting	85.00	c
1 pc	RH front stabilizer bar linkage	95.00	c
1 pc	RH front upper arm	320.00	c
1 pc	RH front knuckle arm	300.00	c
1 pc	RH front lower arm	310.00	c
1 pc	RH front lower arm balljoint attachment	75.00	c
1 pc	RH front tie rod	125.00	c
1 pc	RH front tie rod end	130.00	c
		5,415.00	
Add 15% :		812.25	
		6,227.25	
1 pc	RH front tyre	260.00	sn
1 pc	RH front rim	450.00	sn
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.		800.00	
To remove aircon condenser, pipes and driers. Vaccum and recharge gas		100.00	
To dismantle and check front under-carriages. To replace affected portions.		180.00	

Con't Page 3 ...

Press any key to continue..

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinh.com.sg

Your Reference : Z21VP05029372
Our Ref : 021645

Page : 3
No. : 32222

To conduct front wheel alignment test.	80.00
--	-------

To putty and respray on affected portions.	800.00
--	--------

To focus headlamps. To check front wiring and lighting operation.	30.00
---	-------

Total :	<u>S\$ 8,927.25</u>
---------	---------------------

Singapore Dollars EIGHT THOUSAND NINE HUNDRED
TWENTY SEVEN AND CENTS TWENTY FIVE Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.