



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC22001577/Kvf3n2	
			Date: 04/05/2022	
			Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SML 9008C
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/22/22/VP05/025469	Excess (\$)	500.00
	Assign From	GERALD POH	Assign Date	18/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA FORTUNER V (A)	c.c	2694
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	MHFZX69G807058911	Colour	METALLIC GREY
	Odometer	121059 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	265/65 R17	YOKOHAMA	8 mm
	L/H Front Tyre	265/65 R17	YOKOHAMA	8 mm
	R/H Rear Tyre	265/65 R17	YOKOHAMA	8 mm
	L/H Rear Tyre	265/65 R17	YOKOHAMA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/02/2022	Inspection Date	18/02/2022
	Survey held at	K KIM HIN AUTO PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A) THE MARKET VALUE IS S\$36,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	